

# **BOARD OF ZONING APPEALS-SITE DESIGN**

**September 1, 2021** 5:00 PM

DEPARTMENT OF PLANNING, PRESERVATION & SUSTAINABILITY www.charleston-sc.gov/bza-sd

\*\*Video and microphone is currently disabled for all attendees.\*\*

This meeting is being recorded.

# **Virtual Meeting Protocol**

Staff will control the slides displayed throughout the meeting.

Applicants, staff, Board members and members of the public should give their name first whenever speaking.

Applicants and members of the public must be sworn in before speaking for the first time.

Only attendees who have registered to speak before the deadline at noon today may speak during the meeting.

Video and microphone have been disabled for all attendees. Attendees will only be given the capabilities to speak when they are called on during the public comment period.

Board members who need to recuse themselves from voting will be temporarily removed from the meeting and readmitted prior to addressing the next item.

If the Board needs to go into Executive Session, they will call into a separate conference line and all video and audio on Zoom will be temporarily turned off until they are ready to return to the regular meeting.

Chat has been disabled for everyone.

This meeting is being recorded.

# Board of Zoning Appeals-Site Design

| Your Boar | d of | Zonina | Appeals-Site | Desian | Members are: |
|-----------|------|--------|--------------|--------|--------------|
|           |      |        | pp           |        |              |

Joel Adrian – Chair, Architectural Pa

Designer

Amanda Graham Barton, Landscape

Architect

Jennifer DeCiantis, Landscape Architect/Certified Arborist Paula Murphy, Layperson,

Previously in land

Development

Ruthie Ravenel, Real Estate

Kelvin Huger, Attorney

Jeff Webb, Civil Engineer

Your City of Charleston Staff are:

Eric Schultz, Board Administrator

Lee Batchelder, Zoning

Administrator

Scott Valentine, TRC Coordinator

Bethany Whitaker, Clerk

The Board of Zoning Appeals—Site Design has the authority to do three things:

- 1. Hear appeals to decisions of the Zoning Administrator;
- 2. Grant special exceptions, a fact finding function of the Board; and
- 3. Grant variances to the Zoning Ordinance if the application meets the hardship test outlined in Section 54-924 of the ordinance.

# **Board of Zoning Appeals-Site Design**

## Requirements for Granting a Variance

A variance may be granted by the Board of Zoning Appeals in an individual case of unnecessary hardship if the Board makes the following findings:

- a. there are extraordinary and exceptional conditions pertaining to the particular piece of property;
- b. these conditions do not generally apply to other property in the vicinity;
- because of these conditions, the application of the ordinance to the particular piece
  of property would effectively prohibit or unreasonably restrict the utilization of the
  property; and
- d. the authorization of a variance will not be of substantial detriment to adjacent property or to the public good, and the character of the district will not be harmed by the granting of the variance.

## **Public Comment**

## Order on Each Application:

- Chair announces each application followed by staff presentation and recommendation.
- Staff will call on applicant to present their application after being sworn in by Chair
- Staff will open the public comment period to receive comments from registered attendees in favor (first spoken, then written). Each speaker will be sworn in by the Chair.
- Staff will then recognize registered attendees for public comments in opposition after speaker is sworn
  in (first spoken, then written).
- Staff will recognize the applicant for a short rebuttal.
- Chair will then close the public comment period and begin Board discussion.

### **Providing Comment:**


- If you submitted a request to speak on an item before the deadline, staff will call your name when it is
  your turn to speak and enable your microphone.
- Your microphone will be disabled after you are done speaking.
- You may only speak once for each item and you must state your name and address for the record
  or you will not be permitted to provide comment.

## **Board Discussion**

- Following public comment period, Board members can make comments, ask questions and make motions.
- After a motion and second, Board members will vote "Aye, in favor" or "Nay, not in favor". If vote is
  not unanimous, Chair will poll each member for their vote. The Chairman shall announce the vote on the
  motion and the final decision on the application.
- If a Board member needs to recuse, he will be temporarily removed from the meeting and placed back in the meeting at the start of the next agenda item.
- If the Board needs to go into Executive Session, they will call into a separate conference line and all
  video and audio on Zoom will be temporarily turned off until they are ready to return to the regular
  meeting.

# Agenda Item #A-1

## Approval of the August 4, 2021 BZA-SD Meeting Minutes.



MADE BY: \_\_\_\_\_ SECOND: \_\_\_\_\_ VOTE: FOR \_\_\_\_ AGAINST \_\_\_\_\_

BOARD OF ZONING APPEALS—SITE DESIGN/AUGUST 4, 2021 B. New applications. 2620 CLEMENTS FERRY ROAD(Cainhoy) APP. NO. 2108-04-B1 (TMS#271-00-01-035) Request a one-year extension of two variances granted by the Board on June 5, 2019. Request a variance from Sec 54-327 to allow the removal of 46 grand trees. Request a variance from Sec 54-330 to allow a reduced impervious construction setback near the bases of 13 grand trees. Owner: Cato Ad Holdings, LLC Applicant: SeamonWhiteside + Associates Zoned GB APPROVED XX WITHDRAWN 0 DISAPPROVED 0 DEFERRED 0 Approval with Staff recommendations and conditions: Extend the previous approval for one-year to 6/5/22. MADE BY: P.Murphy SECOND: A.Barton VOTE: FOR 5 AGAINST 0 2310 HENRY TECKLENBURG DRIVE(W. Ashley) APP. NO. 2108-04-B2 (TMS#309-00-00-262) Request a variance from Sec 54-327 to allow the removal of six grand trees. Request a special exception from Sec 54-327 to allow the removal of one grand tree. Owner: Dominion SC Applicant: Forsberg Engineering & Surveying, Inc. Zoned PUD APPROVED XX WITHDRAWN 0 DISAPPROVED 0 DEFERRED 0 Approval with Staff recommendations and conditions Must plant 151 caliper inches of native canopy trees on the project site; landscape plan to be approved by both DRB (sites only) and TRC. Must use 4' chain-link fence as tree protection barricades, Must maintain as many non-grand trees as possible in the narrow strip adjacent to the CWS access easement and project elements. Must have a Certified Arborist treat and prune all protected and grand trees to be preserved on the site. The site plan is to be further developed to satisfy the other requirements of the PUD. Provide a landscape plan to be approved by both DRB and TRC. MADE BY: J.Webb SECOND: P.Murphy VOTE: FOR 5 AGAINST 0 CENTRAL PARK ROAD(James Island) APP. NO. 2108-04-B3 (TMS#340-03-00-007) Request a special exception from Sec 54-327 to allow the removal of one grand tree. Owner: Central Park Road, LLC

BOARD OF ZONING APPEALS—SITE DESIGN/AUGUST 4, 2021

MOTION: Deferral.

MADE BY: ABarton SECOND: J.Webb VOTE: FOR 5 AGAINST 0

4. 70 LINE STREET(Cannonborough/Elliottborough) (TMS#450-04-04-021, 022, 090-092, 100 &102)

Request a special exception from Sec 54-327 to allow the removal of two grand trees. Owner: The Twisted Bubble, LLC Applicant LS3P Zoned GB-A

APPROVED 0 WITHDRAWN XX DISAPPROVED 0 DEFERRED 0

MOTION: Withdrawn.

MADE BY: \_\_\_\_\_\_ SECOND: \_\_\_\_\_ VOTE: FOR \_\_\_\_\_ AGAINST \_\_\_\_\_\_

In accordance with the Americans with Disabilities Act, people who need alternative formats, ASL (American Sign Language) Interpretation or other accommodation please contact Janet Schumacher at (843) 577-1389 three business days prior to the meeting.

Source of Zoning Appendor Foge 1 Source of Zoning Appendor - Site Design Agendor Foge 2 Source of Zoning Appendor - Site Design Agendor Foge 3

WITHDRAWN 0

DEFERRED XX

Applicant: Lesemann & Associates, LLC

Zoned SR-1 APPROVED 0

DISAPPROVED 0

# Agenda Item #A-2

75 CHADWICK DRIVE (South Windemere)

TMS # 421-09-00-019

Request a variance from Sec 54-327 to allow the removal of two grand trees.



Application for Variance, Special Exception, Reconsideration, or Extension to the **Board of Zoning Appeals – Site Design (BZA-SD)** 

Page 1 of 2

City of Charleston

**Instructions –** Submit this application, along with the required information and fee, to the Permit Center at 2 George Street. **Applications are due by 12 Noon on the deadline date and <u>must</u> be complete to be accepted and placed on an agenda.** A sign will be posted on the property, and a public hearing will be conducted by the Board of Zoning Appeals–Site Design. **Permits authorized by the Board cannot be issued during a five (5) business day appeal period following the decision of the Board.** An appeal to the Board during this five (5) business day appeal period stays all further action on the application.

| during this live (3) business day appear period stays air furthe  | a action on the application.   |
|---|--|
| THE APPLICANT HEREBY REQUESTS:  ☐ A Variance and/or Special Exception as explained on p ☐ Tree Removal ☐ Landscaping/buffers ☐ Parkin ☐ Reconsideration of a decision of the Board or action of ☐ Extension of an unexpired Variance and/or Special Exception   | ng surface   |
| MEETING DATE REQUESTED: July 7, 2021  |  |
| Property Address: 75 Chadwick Drive, Charleston, SC 29407   | TMS # 421-09-00-019  |
| Property Owner: Thomas and Courtney Wagoner   | Daytime Phone <u>706-829-9956</u>  |
| Applicant : Elizabeth Pope  | Daytime Phone 803-920-4618   |
| Applicant's Mailing Address: 164 Market Street, #264 Charles  | ston, SC 29401   |
| E-mail  | Address : epopelandscapearchitect@gmail.com  |
| Relationship of applicant to owner: landscape architect   |  |
| Zoning of property: <u>SR-1</u>   |  |
| Information required with application: [check information submitted Scaled site plan or plat showing the variance(s) or special exity Photographs of the site, grand trees to be removed, quality (a) For requests to remove trees, evaluations/reports from certifed Check, credit card or cash (make checks payable to the City of TES of X NO - Is this Property restricted by any recorded corproposed land use encompassed in this permit application? § | trees to be saved by removing others, etc.<br>fied or qualified arborists<br>of Charleston)<br>wenant that is contrary to, conflicts with or prohibits the |
| Optional but <u>very helpful</u> information:  Letters or petitions from neighbors or organizations directly  | affected by your request   |
| I certify that the information on this application and a improvement(s) comply with private neighborhood covenan subject property or the authorized representative of the ow with a notice of the hearing before the Board and inspected.  Applicant  | its, if there are any, and that I am the owner of the<br>ner. I authorize the subject property to be posted  |
| For office use only Date application received Staffperson Fee \$  | Time application received  |

BZA-SD Application (continued)

Page 2 of 2

For **Variance** requests, applicants should list the specific variance(s) being requested and, if possible, explain how the variance test that follows is met (add as an attachment if necessary):

I am requesting the removal of two trees considered grand by the City of Charleston. One is a 28" bald cypress tree. The trunk of this tree is less than one foot from the main water line and seventeen feet from the house foundation. Bald cypress trees are known for their above ground, knotty knee, aggressive, spreading, root habit. This extensive system is going to cause damage to the water line and house foundation very soon. In the past year I have already had one client have to replace their water line after a bald cypress root cut through their water line. I would like to prevent seeing this again. Bald cypresses are beautiful trees. But, they are not meant for small neighborhood gardens. Please see the photos of the above ground roots and proximity to the water line. The second tree is a 31" bradford pear. It is in failing health. James Critikos, an arborist, has urged for the tree to be immediately removed. Both trees have also been detrimentally cut by Dominion Energy for the power lines. Please see the letter attached.

Variance Test: The Board of Zoning Appeals-Site Design is authorized to approve a variance from the requirements of the Zoning Ordinance when strict application of the provisions of the ordinance would result in unnecessary hardship. A variance may be granted in an individual case of unnecessary hardship if the Board makes the following findings:

- There are extraordinary and exceptional conditions <u>pertaining to the particular piece of property</u>:
- 2. These conditions do not generally apply to other property in the vicinity;
- Because of these conditions, the application of the ordinance to the particular piece of property would effectively prohibit or unreasonably restrict the utilization of the property; and
- The authorization of the variance will not be of substantial detriment to adjacent property or to the public good, and the character of the district will not be harmed by the granting of the variance.

In granting a variance, the Board may attach to it such conditions regarding the location, character, or other features of the proposed building, structure, or use as the board may consider advisable to protect established property values in the surrounding area or to promote the public health, safety, or general welfare. (SC Code of Laws Section 6-29-800)

| documer | ntation to demoi | nstrate complian | ice with the re | levant special ex | oval(s) being requi<br>ception requireme<br>ittachment if neces | nts of the Zonin |
|---------|------------------|------------------|-----------------|-------------------|---|------------------|
|         |                  |                  |                 |                   |   |                  |
|         |                  |                  |                 |                   |   |                  |
|         |                  |                  |                 |                   |   |                  |
|         |                  |                  |                 |                   |   |                  |
|         |                  |                  |                 |                   |   |                  |

All approvals of the Board shall remain valid for two (2) years from the approval date, unless extended in accordance with the provisions of Article 9, Part 5 of the zoning ordinance. Applicants may not apply for the same request that has been denied by the Board until a period of six (6) months has lapsed.

### BOARD OF ZONING APPEALS SITE DESIGN

City of Charleston

Wednesday, September 1, 2021

ITEM A 1

75 Chadwick St

(South Windermere)

TMS# 421-09-00-019

ZONED SR-1







## 75 Chadwick Drive











Per Company of the Co **₽** The Wagoner Residence

estrang sate plan sheet 1

existing bradford pear tree in bad health



existing bradford pear tree's spitting bark



existing bradford pear tree's weakened center union



existing bold cypress tree and bradford pear tree seen cut by Dominton Energy

blue marks show knee roots from bold cypress tree, water line is directly below these knee roots.



existing bold cypress tree as seen in close proximity to main water line



existing board cypress tree and bradford pear tree seen cut by Dominton Energy

James Critikos ISA Certified Arborus SC-65729 26 Parlausod Arborus Uharkoton, 3C 25408 643-603-0264

#### CS/20/8021

Mc. and Mrs. Wagerer 23 Chadwell Delve Characton, IZ 35487 883-921-9612

As the request of Mar. Market Pape, another perificies, invocator a large and sharest 50° all fact Opposite phases in the center of the last of Mar. Wagnest in heart part in that is bested 1°° from the thomse and resource 50° CBM. A savely we constant is being a water than in some of the last than a fact their interiors the size of an electrical phase and the savel of the size of the mainter of an electrical phase and the size of the

To the right of this Opens on experience Enabled Rev., In "Dist, late decline in covered entity due to so git had excelled herit at your as footborn attachments attachments with the office of weakening the opens of may other lands. This matrix then has even based Commission to cutsway along excellent after most of the time capacide order, and comment from the other lands have to seed in all some interpretations and its revertile within commenty. This is ten in well inseed to righting, coulpying the to the regardation and the containty in its lights to be homeowhere is so well in the it is extinct obtained of their registroids and the containty in its lights to the homeowhere is on well in the district obtains of their registroids. District in the containty of t

Shandiy

Junes Citiling

The Wagoner Resi

alks to shed

Ambell sopi byłospi od ted. E. 194 mpał Sasz. a 284 d stępa, k. 2741



Der CS-GS-CT man

dence

James Critikos ISA Certified Arborist SO-6572A 29 Parkwood Avenue Charleston, SC 29403 843-693-3184

05/20/2021

Mr. and Mrs. Wagoner 75 Chadwick Drive Charleston, SC 29407 803-920-4618

At the request of Mrs. Elizabeth Pope, landscape architect, I inspected a large and vibrant 60'tall Bald Cypress planted in the center of Mr. and Mrs. Wagoner's front yard. This tree is located 17' from their home and measures 28" DBH. A survey was conducted showing a water line is running within less than a foot from the tree's main trunk and extends directly towards the home parallel with the sidewalk. This species is well known for displaying numerous knees surrounding the entire tree and are evidenced within a foot from the home foundation. The close proximity of the tree clearly indicates further extensive damage will occur to the underground plumbing. This tree has indeed outgrown its function and it is no longer suitable to adapt or thrive in this restricted area. I highly recommend Mr. and Mrs. Wagoner to contact the City of Charleston and seek a permit for its removal.

To the right of this Cypress an enormous Bradford Pear, 31" DBH, is in decline. Its overwhelming size has split and cracked bark at various locations around branch attachments with the effect of weakening the unions of many outer leads. This massive tree has even forced Dominion to cut away a large section of the reach of the tree to provide safety and clearance from both the lower telephone line as well as the upper high-power lines which service the entire community. This tree is well known for splitting, collapsing due to its magnitude and it is certainly a liability to the homeowners as well as to the entire structure of their residence. In addition, its demise could clearly destroy some or all of existing utilities extending towards Chadwick Drive. The removal of this Bradford Pear is highly advisable and action should be pursued in a timely manner.

Sincerely,

James Critikos

### New information



1000 Johnnie Dodds Blvd., STE 103-327 Mt. Pleasant, SC 29464 www.origincause.us SC COA #6262

08/18/2021

Mr. Thomas Wagoner

Via email: twagoner@middlestreet.com

Re: Origin Cause #: 10-21030

Structural Inspection - Tree Root Damage

75 Chadwick Drive, Charleston, South Carolina 29407

Dear Mr. Wagoner:

Per your request, on August 16, 2021, Origin Cause LLC, completed a limited visual inspection of the residential structure located at 75 Chadwick Drive, Charleston, South Carolina. The primary emphasis of the inspection was to evaluate the foundation for existing or impending damages from Bald Cypress tree root growth.

#### **BACKGROUND**

The subject residence was a one-and-half story, wood-framed structure supported on a crawlspace foundation system. The exterior walls were clad with brick veneer and the roof was covered with asphalt composition shingles. According to Charleston County Records, the residence was constructed in 1954 and consisted of approximately 1761 square feet of finished area. Measurements and observations were completed during the inspection to identify existing construction, with photographic evidence of conditions present during the inspection retained for records. For purposes of this report, the front of the residence was referenced to face west, toward Chadwick Drive.

#### SITE INSPECTION OBSERVATIONS

- The Bald Cypress tree of reported concern was located approximately 20 feet to the west of the front elevation.
  - The tree had an approximate trunk diameter of 28 inches in diameter and was estimated to be approximately 60 feet tall.
  - "Kneed" tree root growth was evident in sporadic locations radiating from the base of the tree, including locations within 1 foot of the front curtain wall of the crawl space and in locations up to 30 feet away from the base.
  - A water meter was observed to be in close proximity to the tree and perpendicular alignment with the front of the residence revealed an estimated water line location within 1 foot of the tree base.


- The brick curtain wall around the crawl space was one-wythe thick.
  - No cracking or separation was observed to the masonry or mortar within the curtain wall facing the Bald Cypress.
  - At elevations above the curtain wall, no cracking or separations were evident in the masonry or mortar.
  - Plastic vapor barrier installation within the crawlspace prohibited observation of the earthen ground behind the curtain wall.
- The interior bedroom in closest proximity to the Bald Cypress is currently utilized as a nursery. No displacement or significantly unlevel conditions were noted in the flooring of the nursery under cursory inspection.

#### ANALYSIS AND CONCLUSIONS

No evidence of current structural damage to the residence from Bald Cypress tree root growth was observed during the site inspection. However, the following conditions were also noted; inherent moist soil conditions prevalent at the property due to proximity to coastal waters and low elevations; existing knee growth at locations near the structural foundation and at distances further away than the measured distance between the tree base and the closest foundation; typical Bald Cypress aggressive root growth patterns. Given these conditions and our professional experience, we opine that it is highly probable that the future tree root growth will push up beneath or against the foundation wall and cause damage to the structure and/or damage to the utility lines providing service to the residence. To abate future property damages, it is our recommendation that the tree be removed.

The conclusions contained within this letter are based on experience and statements provided by others. Should additional information become available or discovered, we reserve the right to amend, alter, or change the letter as warranted by the additional information.

Kind Regards,



Casey A. Sams, P.E. Origin Cause LLC

Mally signed by Casey A Sams, PE EN OU=Origin Cause, O=Origin Cause LLC, CN="Casey A Sams, PE", E=cas@origincause.us Reason: I am the author of this document

Location: Home Office Date: 2021-08-18 16:07:06

Foxit PhantomPDF Version: 9.5.0

Thomas Wagoner Page 2 75 Chadwick Dr. 08/18/2021 Cause Origin LLC File # 10-21030

### **New information**





Dote::03-18-21 ecp Rev:: 04-08-21 ecp 04-22-21 ecp 05-26-21 ecp 05-7-21 ecp





existing site plan

sheet 1

# Agenda Item #B-1

20 EHRHARDT DRIVE (Medical District)

TMS # 460-15-01-017, 023-027

Request a variance from Section 54-327 to allow the removal of two grand trees.

Request a special exception from Section 54-327 to allow the removal of two grand trees.

Request a variance from Section 54-327 to omit the 15 protected trees per acre requirement.

**Zoned LB** 



Application for Variance, Special Exception, Reconsideration, or Extension to the Board of Zoning Appeals - Site Design (BZA-SD)

Page 1 of 2

City of Charleston

Instructions - Submit this application, along with the required information and fee, to the Permit Center at 2 George Street. Applications are due by 12 Noon on the deadline date and must be complete to be ed

| accepted and placed on an agenda. A sign will be post conducted by the Board of Zoning Appeals—Site Design. Peduring a five (5) business day appeal period following the during this five (5) business day appeal period stays all further  | rmits authorized by the Board cannot be issued<br>be decision of the Board. An appeal to the Board  |
|---|---|
| THE APPLICANT HEREBY REQUESTS:  ☑ A Variance and/or Special Exception as explained on p ☑ Tree Removal ☐ Landscaping/buffers ☐ Parkin ☐ Reconsideration of a decision of the Board or action of ☐ Extension of an unexpired Variance and/or Special Exception   | ng surface  |
| MEETING DATE REQUESTED: September 1, 2021   |   |
| Property Address 20 Ehrhardt Street   | TMS # 460-15-01-023 and -024  |
| Property Owner The Medical University of SC   | Daytime Phone   |
| Applicant Waldron Engineering and Construction, Inc ATTN: Mich  | nael Mark Daytime Phone 603-772-7153 x 113  |
| Applicant's Mailing Address 37 Industrial Drive, Suite G-1, Exeter  | , NH 03833 mail Address MMark@waldron.com   |
| Relationship of applicant to owner (same, representative, pro   | espective buyer, other) Engineering - Representative  |
| Zoning of property _LB  | , , ,   |
| Information required with application: (check information submitt  Scaled site plan or plat showing the variance(s) or special ex Photographs of the site, grand trees to be removed, quality For requests to remove trees, evaluations/reports from certif  Check, credit card or cash (make checks payable to the City  YES or NO - Is this Property restricted by any recorded coproposed land use encompassed in this permit application? § | ception(s) being requested (3 sets)<br>trees to be saved by removing others, etc.<br>fied or qualified arborists<br>of Charleston)<br>venant that is contrary to, conflicts with or prohibits the |
| Optional but <u>very helpful</u> information:<br>n/a ☐ Letters or petitions from neighbors or organizations directly  | affected by your request  |
| I certify that the information on this application and improvement(s) comply with private neighborhood covenar subject property or the authorized representative of the ow with a notice of the hearing before the Board and inspected.   | nts, if there are any, and that I am the owner of the<br>ner. I authorize the subject property to be posted   |
| Applicant Michael L. Mark   | Date_ July 30, 2021   |
| For office use only Date application received   | Time application received   |

Department of Planning, Preservation & Sustainability 2 George Street Charleston, South Carolina 29401

www.charleston-sc.gov

(843) 724-3781 FAX (843) 724-3772

**BZA-SD Application** (continued) Page 2 of 2

| Requ   | st variance to section 54-327 to remove two (2) grand trees AND remove protected tree preservation requirements   |
|--|---|
| See a  | tached narrative.   |
|  |   |
|  |   |
|  |   |
|  |   |
| requirin unr<br>make:<br>1.<br>2.<br>3.<br>4.<br>In gra<br>featur<br>prope | ce Test: The Board of Zoning Appeals-Site Design is authorized to approve a variance from the ments of the Zoning Ordinance when strict application of the provisions of the ordinance would result ecessary hardship. A variance may be granted in an individual case of unnecessary hardship if the Board the following findings:  There are extraordinary and exceptional conditions pertaining to the particular piece of property: These conditions do not generally apply to other property in the vicinity; Because of these conditions, the application of the ordinance to the particular piece of property would effectively prohibit or unreasonably restrict the utilization of the property; and The authorization of the variance will not be of substantial detriment to adjacent property or to the public good, and the character of the district will not be harmed by the granting of the variance.  In this a variance, the Board may attach to it such conditions regarding the location, character, or other sets of the proposed building, structure, or use as the board may consider advisable to protect established by values in the surrounding area or to promote the public health, safety, or general welfare. (SC Codes Section 6-29-800) |
| docur  | <b>recial Exception</b> requests, applicants should list the specific approval(s) being requested and including the nentation to demonstrate compliance with the relevant special exception requirements of the Zoning ance, such as Sec. 54-329, Sec. 54-511(b), or Sec. 54-513 (add as an attachment if necessary):   |
| Reque  | t special excpetion to section 54-327 to allow for the removal of two (2) grand trees).   |
| See at   | ached narrative.  |
|  |   |
|  |   |
|  |   |
|  |   |

All approvals of the Board shall remain valid for two (2) years from the approval date, unless extended in accordance with the provisions of Article 9, Part 5 of the zoning ordinance. Applicants may not apply for the same request that has been denied by the Board until a period of six (6) months has lapsed.



July 30, 2021

Mr. Eric Schultz TRC Administrator City of Charleston Planning 2 George Street Charleston, SC 29401

Re: MUSC Cogeneration Plant (TMS Nos. 460-15-01-023, -024, -025, -026, and -027)

Grand Tree Removal Variance/Special Exception Request

TRC Project No. Pending

Mr. Schultz:

This letter is provided to summarize the variance/special exception submittal request for the above referenced project.

#### Project Summary:

The project is a combined heat and power facility that will serve the bulk of the existing (and planned) MUSC campus with electrical power and steam. By cogenerating these two utility products within the same facility and recovering the waste heat that is a byproduct of the electrical power generation to reduce boiler fuel consumption, the overall efficiency that is achieved will be considerably higher than that of a conventional approach. This will not only reduce the cost of the University's energy, but will reduce the University's Greenhouse Gas Emissions as well. In addition, the facility will be capable of powering the bulk of the campus and associated medical facilities in the event of an electric utility outage, contributing significantly to the University's operating resiliency.

#### Site Selection:

An extensive site selection process was performed before selecting the site presented herein, for which two variances and a special exception (described below) are being requested. The attached Site Map (BZA Exhibit 0) shows the sites considered, and below is a description of the difficulties associated with each. In general, the project siting requires access to existing utility infrastructure, a footprint of nominally 200' x 100' and minimal interference with the developing Master Plan that supports the core mission of the University. At a high level, all of the sites considered were encumbered by protected trees and/or other programmatic requirements associated with the Master Planning effort that is in process. The site selected was the only feasible site for this energy facility that preserved the University's long-term plans for on-campus growth.

Option 1: Option 1 was briefly considered because of its proximity to multiple existing utilities, including an existing Substation Building across the street. However, the location contains more challenges with trees than the selected site, and it also conflicts with a planned north-south pedestrian corridor that would connect the parking garage(s) to the north with the core of the campus.

MUSC Cogeneration Plant July 30, 2021 Page **2** of **4** 

- Option 2: One option considered was to expand the existing Central Energy Plant located at the intersection of Bee Street and Bravo Street. There were multiple challenges with this site. The proposed cogeneration equipment could not fit in the existing building; the existing Central Energy Plant cannot support the expected campus growth; and constructing the facility on property to the west would interfere with the City's planned stormwater drainage tunnel. In addition, this site would require public parking access beneath the facility and more critically, would be remote from the electrical infrastructure to which it must be connected.
- Option 3: The "M Lot" on the east side of Courtenay Drive was considered, but a parking garage has already been designed for this location by the University. Loss of this garage would significantly impact the University's plans for the future and increase the challenge of ensuring parking for the growing campus. Also, the combined heat and power facility could not fit vertically on the site without encroaching on flight paths to the adjacent heliport.
- Option 4: Option 4, at the intersection of Bee Street and President Street, was considered briefly. However, this would locate the plant directly on Bee Street, a busy public thoroughfare; the site is also more remote from critical utility interconnections; and existing green space at this location would be lost. This location also contained a total of four (4) grand trees and two larger protected trees, all having a health of "Grade B".

#### Variance/Special Exception Request:

The site selection process identified above limited the location of the cogeneration plant to the site currently proposed on MUSC's campus. The project team has worked to minimize the overall footprint to comply with applicable zoning and stormwater requirements. A total of four (4) grand trees are currently being proposed for removal.

The proposed project area only contains two (2) protected trees. As such, a variance request to meet tree protection/preservation requirements identified in Section 54-237.C of the Zoning Ordinance is requested.

The Client engaged Forrest Evans, ISA Certified Arborist with Natural Directions, LLC to provide a tree assessment for the project. This assessment was performed on June 7, 2021 and has been provided on the BZA Exhibit 3 and incorporated into BZA Exhibit 1 and 2. Subsequently, the city and project team performed a site visit on July 2, 2021.

Based on the above information the following variances/special exceptions are being requested to section 54-327 of the City of Charleston Zoning Ordinance and identified on BZA Exhibit 1 and BZA Exhibit 2:

- Variance Request
  - o Grand Tree removal:
    - Tree No. 9 –25" Live Oak Grade "B"
    - Tree No. 10 25" Live Oak Grade "C"

MUSC Cogeneration Plant July 30, 2021 Page **3** of **4** 

- Tree Protection Requirements:
  - Remove protected tree preservation requirements of fifteen (15) trees per acre and/or preservation total number of protected trees onsite.
- Special Exception Request
  - Grand Tree removal:
    - Tree No. 7 − 22/31" Elm − Grade "C"
    - Tree No. 11 11/32.5" Elm Grade "B"

#### Variance Test:

 There are extraordinary and exceptional conditions pertaining to the particular piece of property;

The site is uniquely situated between the utility electrical substation (across Bee Street to the north) and the existing University electrical distribution switchgear building (borders the project site to the south), which will enable the project to effectively "intercept" the existing electrical feeders to campus with minimal disruption, and consolidate campus electrical distribution. The existing electrical feeders are directly adjacent to the proposed site.

The site is also centrally located relative to the existing campus steam generation facilities that will be interconnected to the energy facility. Steam will be distributed from the facility to each of four existing steam plants and/or distribution lines on campus, and the central location will the size and extents of new piping infrastructure required.

2. These conditions do not generally apply to other property in the vicinity;

With regards to the electrical system, other locations would require more extensive infrastructure extensions to facilitate the necessary interconnections. Additionally, due to the nature of the development and the site selection process identified above, the site proposed provides the best opportunity to generally meet the needs of the project while otherwise satisfying local zoning requirements. The site selected was the only feasible site for this energy facility that also preserved the University's long-term plans for on-campus growth.

 Because of these conditions, the application of the ordinance to the particular piece of property would effectively prohibit or unreasonably restrict the utilization of the property;

The trees proposed for removal are located on the interior portions of an urban lot slated for infill. Preservation of the trees would be impossible given any proposed construction. Additionally, any trees located on the fringes of the proposed structure would be impacted during construction causing irreparable damage to the trees.

 The authorization of the variance will not be of substantial detriment to adjacent property or to the public good, and the character of the district will not be harmed by the granting of the variance. MUSC Cogeneration Plant July 30, 2021 Page 4 of 4

The variance and special exceptions request will not be of substantial detriment to adjacent properties since the proposed development is in conjunction with the Medical University's ongoing master planning efforts.

#### Mitigation Requirements:

Where possible, onsite mitigation will be provided, however, it is anticipated that a majority of the mitigation requirements specified will be fulfilled on areas within MUSC's campus outside of the project area. Locations to be determined in conjunction with the MUSC Arboretum Program.

Should you have any questions or require additional information, please do not hesitate to call me at (843) 270-3185.

Sincerely,

Cameron Baker, PE

Can B. Bah

Principal

### BOARD OF ZONING APPEALS SITE DESIGN

City of Charleston Wednesday, September 1, 2021


ITEM B 1 20 Ehrhardt St

(Medical District)


TMS# 460-15-01-017, 023-027

ZONED LB







## 20 Ehrhardt Drive












BZA0






### BZA EXHIBIT 3 - NATURAL DIRECTIONS TREE ASSESSMENT REPORT


| Tree Number | DBH     | Speices      | Grade | Comments       | Comments        | Condition |
|-------------|---------|--------------|-------|----------------|-----------------|-----------|
| 1           | 28.5    | Live Oak     | В     | Utility Pruned | Decline         | Good      |
| 2           | 31.5    | Live Oak     | В     | Utility Pruned | Decline         | Good      |
| 3           | 20.5    | Bald Cypress | В     |                |                 | Good      |
| 4           | 25.5    | Bald Cypress | В     |                |                 | Good      |
| 5           | 19.5    | Bald Cypress | В     | Vines          |                 | Good      |
| 6           | 35      | Laurel Oak   | В     | Decay          |                 | Good      |
| 7           | 22/31   | Elm          | С     | Decay          | V Shaped Crotch | Fair      |
| 8           | 20      | Laurel Oak   | С     | Decay          | Sweep           | Fair      |
| 9           | 25      | Laurel Oak   | В     |                | 33.33-36.0      | Good      |
| 10          | 25      | Laurel Oak   | С     | Forked         |                 | Fair      |
| 11          | 11/32.5 | Elm          | В     |                |                 | Good      |




TREE NO. 7











TREE NO. 11





# Agenda Item #B-2

F STREET

(Westside)

TMS # 460-04-04-118

Request a variance from Section 54-327 to allow the removal of two grand trees.

Request a special exception from Section 54-327 to allow the removal of two grand trees.

Request a variance from Section 54-327 to omit the 15 protected trees per acre requirement.

Zoned MU-1/WH



Application for Variance, Special Exception, Reconsideration, or Extension Page 1 of 2 to the Board of Zoning Appeals - Site Design (BZA-SD)

### City of Charleston

Instructions - Submit this application, along with the required information and fee, to the Permit Center at 2 George Street. Applications are due by 12 Noon on the deadline date and must be complete to be rd

| □ Reconsideration  | oval Dandscaping/buffers Parking<br>on of a decision of the Board or action of a<br>on unexpired Variance and/or Special Exce   | zoning official (attach A   | ppeal form).  |
|--|---|---|---|
| EETING DATE REC  | OUESTED: September 1.2021   |   |   |
| operty Address _   | 676 King Street   | TMS #460-04-04-118  |   |
| operty Owner   | City of Charleston  | Daytime Phone   |   |
| pplicantFor  | sberg Engineering & Surveying, Inc  | Daytime Phone   | 843-571-2622  |
| pplicant's Mailing /   | AddressPO BOX 30575, CHARLES  | STON, SC 29417  |   |
|  | F ****  | ail Addresstlinton@fc   | orchera engineering co  |
|  | vith application: (check information submitted  |   |   |
| <ul> <li>Scaled site plan</li> <li>Photographs of</li> <li>For requests to</li> <li>Check, credit ca</li> <li>YES or</li> <li>NO -</li> <li>proposed land use</li> </ul>       | or plat showing the variance(s) or special except the site, grand trees to be removed, quality treemove trees, evaluations/reports from certified or cash (make checks payable to the City of sthis Property restricted by any recorded coverencempassed in this permit application? § 6- | es to be saved by removing<br>d or qualified arborists<br>(Charleston)<br>enant that is contrary to, con  | g others, etc.  Inflicts with or prohibits th   |
| Scaled site plan  Photographs of  For requests to  Check, credit ca  PES or NO -  proposed land use  | the site, grand trees to be removed, quality tre<br>remove trees, evaluations/reports from certified<br>rd or cash (make checks payable to the City of<br>is this Property restricted by any recorded cove<br>encompassed in this permit application? § 6-                                | es to be saved by removing<br>d or qualified arborists<br>Charleston)<br>enant that is contrary to, col<br>29-1145 of the South Carol   | g others, etc.  Inflicts with or prohibits th   |
| Scaled site plan  Photographs of For requests to Check, credit ca YES or S NO - proposed land use ptional but very help Letters or petitic certify that the inprovement(s) com | the site, grand trees to be removed, quality tre<br>remove trees, evaluations/reports from certified<br>rd or cash (make checks payable to the City of<br>is this Property restricted by any recorded cove<br>encompassed in this permit application? § 6-<br>ful information:            | res to be saved by removing d or qualified arborists Charleston) remant that is contrary to, coicled the South Carol fected by your request for a stackments is correst, if there are any, and the subject. | g others, etc.  Inflicts with or prohibits the code of Laws  ect, that the propose at I am the owner of the |
| Scaled site plan  Photographs of  For requests to  Check, credit ca  PES or NO -  proposed land use  | the site, grand trees to be removed, quality tre<br>remove trees, evaluations/reports from certified<br>rd or cash (make checks payable to the City of<br>is this Property restricted by any recorded cove<br>encompassed in this permit application? § 6-<br>ful information:            | es to be saved by removing<br>d or qualified arborists<br>Charleston)<br>enant that is contrary to, col<br>29-1145 of the South Carol   | g otr   |

BZA-SD Application (continued) Page 2 of 2

|  | Applicant requests variance to section 54-327c (removal of 2 Grand trees)  |
|--|--|
|  | Applicant also requests removal of protected trees and protection of 15  |
|  | tees/acre requitement  |
|  |  |
| the requirement<br>result in unneces           | The Board of Zoning Appeals-Site Design is authorized to approve a variance from<br>its of the Zoning Ordinance when strict application of the provisions of the ordinance would<br>ssary hardship. A variance may be granted in an individual case of unnecessary hardship if the<br>e following findings:  |
| These co.     Because effectively     The auth | e extraordinary and exceptional conditions <u>pertaining to the particular piece of property</u> ; nditions do not generally apply to other property in the vicinity; of these conditions, the application of the ordinance to the particular piece of property would by prohibit or unreasonably restrict the utilization of the property; and property or to the property or to the property or the condition of the variance will not be of substantial detriment to adjacent property or to the property or the condition of the character of the district will not be harmed by the granting of the variance. |
| features of the p                              | riance, the Board may attach to it such conditions regarding the location, character, or other<br>proposed building, structure, or use as the board may consider advisable to protect established<br>in the surrounding area or to promote the public health, safety, or general welfare. (SC Code<br>6-29-800)  |
| documentation                                  | <b>eption</b> requests, applicants should list the specific approval(s) being requested and include to demonstrate compliance with the relevant special exception requirements of the Zoning as Sec. 54-329, Sec. 54-511(b), or Sec. 54-513 (add as an attachment if necessary):   |
|  | Special exception see 54-327 removal of 2 grand trees (2 sycamore trees)   |
|  |  |
|  |  |

in accordance with the provisions of Article 9, Part 5 of the zoning ordinance. Applicants may not apply for the same request that has been denied by the Board until a period of six (6) months has lapsed.

### BOARD OF ZONING APPEALS SITE DESIGN

City of Charleston Wednesday, September 1, 2021


ITEM B 2 F St

(Westside)


TMS# 460-04-04-118

ZONED MU-1/WH






F Street






















# Agenda Item #B-3

MAYBANK HIGHWAY (Johns Island)

TMS # 279-00-00-55-057

Request a variance from Section 54-327 to allow the removal of three grand trees.

Request a special exception from Section 54-327 to allow the removal of 14 grand trees.

Request a variance from Section 54-327 to allow a reduced landscape buffer.

Zoned DR-6



#### Application for Variance, Special Exception, Reconsideration, or Extension to the Board of Zoning Appeals - Site Design (BZA-SD)

City of Charleston

Instructions - Submit this application, along with the required information and fee, to the Permit Center at 2 George Street. Applications are due by 12 Noon on the deadline date and must be complete to be accepted and placed on an agenda. A sign will be posted on the property, and a public hearing will be conducted by the Board of Zoning Appeals-Site Design. Permits authorized by the Board cannot be issued during a five (5) business day appeal period following the decision of the Board. An appeal to the Board during this five (5) business day appeal period stays all further action on the application.

| THE APPLICANT HEREBY REQUESTS:  A Variance and/or Special Exception as explained of Tree Removal  Landscaping/buffers Par   | on page 2 of this form.  |
|---|--|
| Reconsideration of a decision of the Board or action Extension of an unexpired Variance and/or Special  | n of a zoning official (attach Appeal form).   |
| MEETING DATE REQUESTED: September 1, 2021   |  |
| Property Address Maybank Highway  | TMS # 279-00-00-055, 056, & 057  |
| Property Owner Middleburg Communitites, LLC   | Daytime Phone  |
| Applicant Dangerfield Engineering & Surveying, LLC  | Daytime Phone 843-509-3337   |
| Applicant's Mailing Address 1250 Brickle Street, Orangebur  | g, SC 29118  |
|   | E-mail Address john@dangerfieldengr.com  |
| Relationship of applicant to owner (same, representative,   |  |
| Zoning of property DR-6   |  |
| <ul> <li>☑ Scaled site plan or plat showing the variance(s) or special</li> <li>☑ Photographs of the site, grand trees to be removed, qual</li> <li>☑ For requests to remove trees, evaluations/reports from ce</li> <li>☑ Check, credit card or cash (make checks payable to the C</li> <li>☐ YES or ☑ NO - Is this Property restricted by any recorded proposed land use encompassed in this permit application?</li> </ul> | lity trees to be saved by removing others, etc.<br>ertified or qualified arborists<br>[ity of Charleston]<br>I covenant that is contrary to, conflicts with or prohibits t |
| Optional but very helpful information:  ☐ Letters or petitions from neighbors or organizations direct   | ctly affected by your request  |
| I certify that the information on this application an<br>improvements comply with private neighborhood cover<br>subject property or the authorized representative of the<br>with a notice of the hearing before the Board and inspect   | nants, if there are any, and that I am the owner of the owner. I authorize the subject property to be poster.  |
| Applicant 271   | Date 8 2 2021  |
| For office use only Date application received Staffperson Fee \$  | Time application received  |
| Department of Planning, Preservation & Sustainability   | 2 George Street Charleston, South Carolina 29401 Www.charleston-sc.gov   |

BZA-SD Application (continued)

Page 2 of 2

For Variance requests, applicants should list the specific variance(s) being requested and, if possible, explain how the variance test that follows is met (add as an attachment if necessary):

Free Removal Variance for 3 Grand Trees Identified on Report as (#56, #57, and #91):

Tree Variance Request #1 (#56 Tree Report)- 39"(18"/21") Red Oak, Grade D, Hollow Base, Decay, Poor Condition, Category 1

Tree Variance Request #2 (#57 Tree Report)- 32" (9"/10"/13") Post Oak, Grade D. Stump Sprouts, Poor Form, Poor Condition, Category 2

Tree Variance Request #3 (#91 Tree Report)- 26" (8"/9"/9"), Live Oak, Grade C, Fair Condition, Category 1

The site heavily wooded with 86 grand trees located within the developable area. The northern portion of the site was timbered in the late 1990s and numerous multi-trunk trees regenerated. The site went through numerous reiterations during the conceptual design to save high quality trees without the use of tree wells. Tree Variance #1 & #2 allows saving the grand trees/significant trees including (23" Live Oak and 18" Laurel Oak) north and south of Pod 9 while also saving and incorporating a number of healthier and more prominent significant trees (16 significant trees) within the internal green space of Pod 9. Tree Variance #3 will allow the drive to be aligned to accommodate a green area around #79, #80, #81 without the use of tree wells and provide a stormwater detention area that utilizes the existing grade without the need for additional fill around POD 10 protected trees

Variance to Remove 25' Type D Buffer Adjacent to SR-1 (TMS #279-00-00-018):

We have included a copy of the National Wetland Inventory maps identifying the area adjacent to the northern boundary line as being wetlands. This area is located within the Stormwater Special Protection Area and the fill of these wetlands would not be practical. In addition, the buffer is being required by ordinance due to the development being considered multi-family. Although Middleburg Communities product falls within the multi-family classification it is a unique concept that utilizes single-family cottages and two story fownhomes that have single-family atmosphere. Reduction of the buffer will also minimize the impact to the grand trees.

Variance Test: The Board of Zoning Appeals-Site Design is authorized to approve a variance from the requirements of the Zoning Ordinance when strict application of the provisions of the ordinance would result in unnecessary hardship. A variance may be granted in an individual case of unnecessary hardship if the Board makes the following findings:

- 1. There are extraordinary and exceptional conditions pertaining to the particular piece of property:
- These conditions do not generally apply to other property in the vicinity;
- 3. Because of these conditions, the application of the ordinance to the particular piece of property would effectively prohibit or unreasonably restrict the utilization of the property; and
- 4. The authorization of the variance will not be of substantial detriment to adjacent property or to the public good, and the character of the district will not be harmed by the granting of the variance.

In granting a variance, the Board may attach to it such conditions regarding the location, character, or other features of the proposed building, structure, or use as the board may consider advisable to protect established property values in the surrounding area or to promote the public health, safety, or general welfare. (SC Code of Laws Section 6-29-800)

For **Special Exception** requests, applicants should list the specific approval(s) being requested and include documentation to demonstrate compliance with the relevant special exception requirements of the Zoning Ordinance, such as Sec. 54-329, Sec. 54-511(b), or Sec. 54-513 (add as an attachment if necessary):

Tree Removal Special Exception:

Special exception to remove trees #8, #16, #22, #55, #66, #73, #74, #77, #78, #82, #92, #93, #100, & #103

The site is heavily wooded with 86 grand trees located within the developable area. The northern portion of the site was timbered in the late 1990s and numerous multi-trunk trees regenerated. The site went through numerous reiterations during the conceptual design to save high quality trees without the use of tree wells. The special exception to remove these trees will allow higher quality significant trees to be saved, allow site configuration to reduce impacts to higher quality grand trees, and allow site grading to prevent the use of tree wells

All approvals of the Board shall remain valid for two (2) years from the approval date, unless extended in accordance with the provisions of Article 9, Part 5 of the zoning ordinance. Applicants may not apply for the same request that has been denied by the Board until a period of six (6) months has lapsed.

### BOARD OF ZONING APPEALS SITE DESIGN

City of Charleston Wednesday, September 1, 2021


ITEM B 3


Maybank Hwy

(Johns Island)


TMS# 279-00-00-055-057


ZONED DR-6







## Maybank Highway







## National Wetland Inventory Maps - The Ha



July 20, 2021

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

# PRELIMINARY PLANS

# THE HAMLET AT MAYBANK HIGHWAY

Dangerfield Engineering & Surveying, LLC 1250 Brickle Street

Orangeburg, SC 29118 803.354.1393

Owner:

#### MIDDLEBURG COMMUNITIES, LLC

341 EAST BAY ST. CHARLESTON, SC 29401 703.291.0300

UTILITY PROVIDERS:

POWER:

BERKELEY ELECTRIC CO-OP 414 N HIGHWAY 52 MONCKS CORNER, SC 29461 (843) 761-8200

ST JOHNS WATER COMPANY 3362 MAYBANK HWY JOHNS ISLAND, SC 29455 (843) 514-8901

DOMINION ENERGY 2390 W. AVIATION AVE NORTH CHARLESTON, SC 29406 (800) 815-0083

COMMUNICATIONS:

975 SAVANNAH HIGHWAY, SUITE 301 CHARLESTON, SC 29407 (877) 737-2478

COMCAST CABLEVISION-LOW COUNTRY 2070 SAM RITTENBERG BLVD CHARLESTON, SC 29407 (843) 405-4275



The South Consider STATE LAW requires that encounters goe of 27—long rottine. Cli switting days receiving weekens and hollegold, been processed, you will know when you are legally five to grouped with the digally want and which stiffline in the creat process with the digally want and within stiffline in the creat process was also as the constraint of the constraint of Companies ask that you leave a 2 1/2 feet margin on each side of a marked utility law. Also nate that your request is good for 15 worklys digar after it has been processed by our system.

## TMS No. 279-00-00-055, 056, & 057 MAYBANK HIGHWAY CITY OF CHARLESTON CHARLESTON COUNTY, SC





### SHEET INDEX

| C001 | SUMMARY TABLE & GRAND TREE REMOVAL | C400 | OVERALL GRADING & STORM DRAINAGE PLAN |
|------|------------------------------------|------|---------------------------------------|
| C101 | TOPOGRAPHIC SURVEY                 | C401 | PARTIAL GRADING PLAN                  |
| C102 | TOPOGRAPHIC SURVEY                 | C402 | PARTIAL GRADING PLAN                  |
| C103 | TOPOGRAPHIC SURVEY                 | C403 | PARTIAL GRADING PLAN                  |
| C104 | TOPOGRAPHIC SURVEY                 | C404 | PARTIAL GRADING PLAN                  |
| C105 | TOPOGRAPHIC SURVEY                 | C500 | OVERALL UTILITY PLAN                  |
| C300 | OVERALL SITE PLAN                  | C501 | PARTIAL UTILITY PLAN                  |
| C301 | TREE CUTTING/SITE PLAN OVERLAY     | C502 | PARTIAL UTILITY PLAN                  |
| C302 | TREE CUTTING/SITE PLAN OVERLAY     | C503 | PARTIAL UTILITY PLAN                  |
| C303 | TREE CUTTING/SITE PLAN OVERLAY     | C504 | PARTIAL UTILITY PLAN                  |
| C304 | TREE CUTTING/SITE PLAN OVERLAY     |      |                                       |

REVISED: AUGUST 12, 2021 **DATE: JULY 16, 2021** 







PRELIMINARY JOHN M DANGERFIELD II P.E. & P.L.S. No. 21620

#### SCOHEC NPDES STANDARD NOTES (2012 CGP).

- IF NECESSARY, SLOPES, WHICH EXCEED EIGHT (8) VERTICAL FRET SHOULD BE STABILIZED WITH SYNTHETIC OR VENETATIVE WATS, IN ADDITION TO HIGHOSEEPING. IT WAY BE NECESSARY TO INSTALL TEMPORARY EXCEPT BRAINS DURING CONSTRUCTION, TEMPORARY DERIVE WAY BE NECESSARY TO INSTALL TEMPORARY DERIVE WAY BE NECESSARY.
- STABILIZATION MEASURES SHALL BE INTIGATIO AS SOON AS PRACTICABLE IN PORTIONS OF THE SITE WEIGH CONSTRUCTION ACTIVITIES HAVE TEMPORARY OF MEMAARCHILY CEARDD, BUT IN NO CASE MORE THAN FORMEDS (10) DAYS STITU BON HAVE CHARLO THE PART STATE OF THE STATE OF
- ALL SEMENT HAS EXISSEN CONTROL DEVICES SHALL BE INSPECTED ONCE CALEDIDAR EVERY WEEK F PRINCIPLE INSPECTION OF OTHER INFORMATION DISCLASES HALT A BUT HAVE BEEN INVERPORATELY, OR INCORRECTLY, THE PREMITTER WILST ACCRESS THE INCESSARY REPLACEMENT OR MICERICATION REQUIRED TO CORRECT THE BMP WHITN OR HOUSE OF EXCHANGE TOW.
- PROVIDE SILT FENCE AND/OR OTHER CONTROL DELYCES, AS MAY BE REQUIRED. TO CONTROL SOIL EROSION DURING UTLITY CONSTRUCTION ALL DESTURBED AFRAS SHALL BE CLEANED, GRACED, AND STRAILED WITH CRASSING MARGINATELY AFFECT BY UTLITY INSTALLATION PILL CORE, AND EMPORARY SEZENCE AT THE DOM'C SLOCK DAY ARE RECOMMENDED, IF WARTS IS DECONTRIBED WHILE TROMOND, HE WASTER SHOULD BE FILTERED TO REMOVE SERVICE SERVICE SERVICE WESTER OF THE STATE.
- ALL BROSON CONTROL SCHICES SHALL BE PROPERLY MAINTAINED SURBIG ALL PHACES OF CONSTRUCTION UNTIL THE COMPLETION OF ALL CONSTRUCTION ACTIVITIES AND ALL DISTURBED APEAS HAVE BEEN STABLLESS. ACCIDITABLE CONTROL DELVISE MAY BE EXCURISED DAINED CONSTRUCTION IN ORDER TO CONTROL EXPOSAN AND/OR OFFITE BOMBNITATION. ALL TEMPORARY CONTROL DELVISES SHALL BE REMOVED ONCE CONSTRUCTION IS COMPLETE AND THE STILL STABLEDS.
- RESIDENTIAL SUBDIVISIONS REQUIPE EROSION CONTROL FEATURES FOR IMPRASTRUCTURE AS NELL AS FOR MINIMUM, LOT CONSTRUCTION INCRIBUM, PROPERTY OWNERS SHALL FOLLOW THESE PLANS DURING CONSTRUCTION OR ORTHON APPROVAL OF AN INDIVIDUAL PLAN IN ACCORDINACE WITH S.C. EGG. 73–739 ET 25G. AND SCRICOSOS.
- TEMPORARY DIVERSION BEAMS AND/OR DITCHES WILL BE PROVIDED AS NEEDED DURING CONSTRUCTION TO PROTECT WORK AREAS FROM UPSLOPE RUNOFF AND/OR TO DIVERT SEDMENT—LAGEN WATER TO APPROPRIATE TRAPS OR STRAKE COURSE.
- ALL BATERS OF THE STATE (BOSS), INCLUDING BETLANDS, ARE TO BE FLAGGED OR OTHERWISE, CLEARLY MARKED THE FEED AN OLDER FORW OF SAFT FEEDER IS TO BE INSTALLED IN MA, AREAS SHEEPS A 505-FOOT BEFFER CANT BE MARTHANDO BETREED THE SETURBED AREA AND ALL MOS. A 10-FOOT BUFFER SHOULD BE WARHTANED BETREED THE LAST FOOK OF SET FEEDE AND ALL MOS.
- 10. LITTER, CONSTRUCTION DEBPIS, OLS, FUELS, AND BUILDING PRODUCTS WITH SIGNIFICANT POTENTIAL FOR IMPACT
- A COPY OF THE SWPPF, INSPECTIONS RECORDS, AND RAINFALL DATA MUST BE RETAINED AT THE CONSTRUCTION SITE OR A NEARPY LOCATION EASILY ACCESSIBLE DURING MORBAIC BUSINESS HOURS, FROM THE DATE OF COMMENCEMENT OF CONSTRUCTION ACT
- INITIATE STABILIZATION MEASURES ON ANY EXPOSED STEEP SLOPE (SH IV OR OREATER) SHERE LAND-DISTANSING ACTIVITIES HAVE PERMANENTLY OR TEMPORARELY CRAIGO, AND WILL NOT RESIME FOR A PERIOD OF 7 CALIDIDAR
- 14 MINIMIZE THE DISCHARGE OF POLLUTANTS FROM EQUIPMENT AND VEHICLE WASHING, WHIEL WASH WATER, AND OTHER WASH WATERS, WASH WATERS MUST BE TREATED IN A SEGMENT BASH OR ALTERNATIVE CONTROL THAT PROVIDES EQUIPMENT OR BETTER TREATMENT PRIOR TO DISCHARGE.

- 10. THE FOLLOWING DISCHARGES FROM STEES AND PROBERTIED:
   MEDITARTIN FROM MEMBERT OF CONSTRUCTION DATES MANAGED BY AN APPROPRIATE CONTROL.
   MEDITARTIN FROM MEMBERT OF STRUCTURE PARTY, FORM FELENCE RES. CHIPMS COMPOUNDS
   POLIS, ORS, OR OTHER POLLUTANTS USED IN MEMBELS AND EXEMPTED TRANSPORT OF MAINTINETS.
   SOUND'S OR SOLWESTS USED IN MEMBELS AND EXEMPTED TRANSPORT.
- 18. F CASTING BMPs NEED TO BE MOCRIFIED OR F ACCITONAL BMPs ARE NECESSARY TO COMPLY BITH THE RECOMPRISENTS OF THIS REPORT MAD/OR SC'S BNEED GUALITY STRADARDS, INVERSITATION MAST BE COURSETED BEFORE THE NEXT STORD ELEMS TREMEDER PRACTICALE. F PARTICIPATIONS BUSINESS THE ACCT STORM EXPORT TO MAPACITIZABLE, THE SUITABLE MAD'T BE SOURCED IN THE SWPPF AND ALTERNATIVE BMPS MOST BE MAPACITIZABLE THE SUITABLE MAD'T BE SOURCED IN THE SWPPF AND ALTERNATIVE BMPS MOST BE MAPACITIZABLE THE SUITABLE MAD'T SOURCE.
- 19. A PRE-CONSTRUCTION COMPRIENCE MUST BE HELD FOR EACH CONSTRUCTION SITE WITH AN APPROVAD ON-SITE SWIPP PRICE TO THE IMPLEMENTATION OF CONSTRUCTION ACTIVITIES FOR MON-LINEAR PROJECTS THAT CISTAME TO ACRES OR MUSIC THIS COMPRIENCE MUST BE HELD ON-SITE URLESS THE DEPARTMENT HAS APPROVED OTHERWISE.

HABS PLACES MY SONITURE SHIP SESS ON THE SEGON DOCUMENTS SEMINTED SON PHINS THAT LOCSET REPONSIBILITY FOR THE SEGON OF THE SMITENT FARTHER, CORTRY TO THE REST OF MY NORMARD SHIP THAT THE SEGON'S CONSESTED WITH THE SEGUNDANCES. OF THE SECONDARY HOST AND COOR OF THIS OF SECONDARY SHAPE WITH SECONDARY DESCRIPTIONS TO THE SECONDARY SHAPE WITH

#### PRELIMINARY

JOHN M. DANGERFIELD, IL P.E. & P.L.S. No. 21620

| AREA SUMMAR                   | Y TABLE |
|-------------------------------|---------|
| UPLAND AREA (ACRES)           | 34.813  |
| WETLAND AREA (ACRES)          | 11.248  |
| WETLAND FILL (ACRES)          | 0.490   |
| TOTAL UPLAND AREA<br>(ACRES)  | 35.303  |
| TOTAL PROJECT AREA<br>(ACRES) | 46.061  |

| PARKING SUM                  | MARY TABLE |  |  |  |
|------------------------------|------------|--|--|--|
| STANDARD                     | 339        |  |  |  |
| H/C PARKING                  | 10         |  |  |  |
| TOTAL REQUIRED<br>(1.5/UNIT) | 317        |  |  |  |
| TOTAL PROVIDED               | 349        |  |  |  |

| UNIT COUNT TABLE |              |                |             |  |  |  |  |  |  |
|------------------|--------------|----------------|-------------|--|--|--|--|--|--|
| BLDG TYPE        | No. OF BLDGS | UNITS PER BLDG | TOTAL UNITS |  |  |  |  |  |  |
| A                | 7            | 2              | 14          |  |  |  |  |  |  |
| B1               | 25           | 1              | 25          |  |  |  |  |  |  |
| B2               | 18           | 1              | 18          |  |  |  |  |  |  |
| В3               | 68           | 1              | 68          |  |  |  |  |  |  |
| C1               | 28           | 1              | 28          |  |  |  |  |  |  |
| TOWNHOMES        | 10           | 4              | 40          |  |  |  |  |  |  |
| TOWNHOMES        | 3            | 6              | 18          |  |  |  |  |  |  |
|                  |              | TOTAL          | 211         |  |  |  |  |  |  |

| UPLAND AREA TREE<br>SUMMARY TABLE   |      |  |  |  |  |  |  |
|---|------|--|--|--|--|--|--|
| SIGNIFICANT TREES   | 999  |  |  |  |  |  |  |
| GRAND TREES   | 91   |  |  |  |  |  |  |
| TOTAL No. OF<br>PROTECTED TREES   | 1090 |  |  |  |  |  |  |
| TOTAL No. OF PROTECTED<br>TREES REQUIRED TO REMAIN<br>(25% OF TOTAL # OF TREES) | 273  |  |  |  |  |  |  |
| TOTAL No. OF<br>PROTECTED TREES<br>TO BE SAVED                                  | 389  |  |  |  |  |  |  |

| Tree Number | DBH (inches)               | Speices                 | Grade      | Comment 1                              | Comment 2                      | Condition    | Category | Proposed Removal | Approval Required            |
|-------------|----------------------------|-------------------------|------------|--|--------------------------------|--------------|----------|------------------|------------------------------|
| 1           | 22/31.5/32                 | Live Oak<br>Live Oak    | 8          | Littlity Pruned<br>Storn Damage        |                                | Good         | 1        | No<br>No         |                              |
| 3           | 11/12/16                   | Water Oak               | D          | Stump Sprouts                          | Decay                          | Poor         | 3        | No.              |                              |
| 4           | 27                         | Red Oak                 | D          | Broken Top                             | Hollew                         | Poor         | 2        | No               |                              |
| - 5         | 11.5/12                    | Live Oak                | 8          | NON GRAND                              |                                | Good         | 1        | No               |                              |
| - 6<br>7    | 14.5/18<br>31.5            | Live Oak<br>Live Oak    | - B        | Vines                                  | Lean                           | Good         | 1        | No<br>No         |                              |
| 8           | 85/39/11                   | Black Cherry            | D          | Stump Sproets                          | Poor Farm                      | Poor         | 4        | Yes              | Special Exception            |
| 9           | 26.5                       | Live Oak                | c          | Hollow                                 | Lean                           | Fair         | 1        | No               |                              |
| 10          | 30.5                       | Water Oak<br>Water Oak  | c          | Decay                                  | Poor Farm<br>Poor Farm         | Fair<br>Fair | 3        | No<br>No         |                              |
| 11          | 55.5                       | Live Oak                | 8          | Decay<br>Storm Damage                  | Poorrams                       | Good         | 1        | No.              |                              |
| 13          | 23.5                       | Laurel Oak              | 8          | NON GRAND                              |                                | Geod         | 2        | Yes              | NA/Significant Tree          |
| 14          | 25                         | Red Oak                 | C          | Crook                                  | PoorFerm                       | Fair         | 2        | No               |                              |
| 15<br>16    | 25<br>29.5                 | Barrel Oak<br>Water Oak | D<br>D     | Poor Form<br>Decay                     | Included Bark<br>Included Bark | Poor         | 3        | No<br>Yes        | Special Exception            |
| 17          | 51                         | Live Oak                |            | Creaty                                 |                                | Good         | 1        | No               | aprent transports            |
| 18          | 26.5                       | Red Oak                 | 8          |  |                                | Good         | 2        | No               |                              |
| 19<br>20    | 27                         | Laurel Oak<br>Red Maple | C E        | NON GRAND                              |                                | Good         | 2        | No.              | NA Winstill cost Toron       |
| 21          | 21<br>25                   | Black Gum               | è          | Storm Damage                           | Poor Farm                      | Fair         | 1        | Yes<br>No        | NA/Significant Tree          |
| 22          | 30                         | Elm                     | D          | Broken Top                             | Sterm Demage                   | Poor         | 4        | Yes              | Special Exception            |
| 23          | 27                         | Red Oak                 |            |  |                                | Good         | 2        | No               |                              |
| 24<br>25    | 30.5<br>23.5               | Black Gum               | C C        | Storm Danage<br>Lean                   | NON GRAND                      | Fair<br>Fair | 2 1      | No<br>No         |                              |
| 26          | 10.5/14.5                  | Live Oak                | - 8        | OF BIT                                 | 14011 0110010                  | Good         | 1        | No               |                              |
| 27          | 26                         | Red Oak                 | B          |  |                                | Good         | 2        | No               |                              |
| 28<br>29    | 25.5                       | Black Gum<br>Maple      | D D        | Crook/Lean<br>Hollow                   | NON GRAND                      | Poor         | 1        | No<br>No         |                              |
| 30          | 15.5/16                    | Live Oak                | 8          | Lean                                   |                                | Good         | 1        | No.              |                              |
| 31          | 31                         | Live Oak                |            |  |                                | Good         | 1        | No               |                              |
| 32          | 18/21.5                    | Live Oak<br>Live Oak    | 8          | Hollow Base                            |                                | Good         | 1        | No<br>No         |                              |
| 34          | 70                         | Live Oak                |            |  |                                | Good         | 1        | No<br>No         |                              |
| 35          | 57.5                       | Live Oak                |            |  |                                | Good         | 1        | No               |                              |
| 36          | 43                         | Red Oak                 | 8          | V thought to the                       | Dane'                          | Geod         | 2 2      | No.              |                              |
| 37          | 12/13<br>29                | Water Oak<br>Laurel Oak | D B        | V-Shaped Crotch                        | PoorFarm                       | Poor<br>Good | 3 2      | No<br>No         |                              |
| 39          | 23.5                       | Weter Oak               | D          | V-Shaped Crotch/Foor Form              | NON GRAND                      | Poor         | 3        | No               |                              |
|             | 10/14/14.5/18.5/26         |                         | 8          |  |                                | Grod         | 1        | No               |                              |
| 41          | 25.5<br>28                 | Weter Oak<br>Laurel Oak | D          | Hollow Base                            | Poor Ferrs                     | Fair<br>Poor | 3        | No<br>No         |                              |
| 43          | 23                         | Water Oak               | D          | Poor Form/Lean                         | NON GRAND                      | Poor         | 3        | No.              |                              |
| 44          | 24.5                       | Lourel Oak              | D          | Hellow                                 |                                | Poor         | 2        | No               |                              |
| 45<br>46    | 13/35                      | Live Oak                | · c        | Utility Pruned                         |                                | Fair         | 1        | No               |                              |
| 46          | 33.5<br>67.5               | Black Gum<br>Live Oak   | 8          |  |                                | Good         | 1        | No<br>No         |                              |
| 48          | 31.                        | Live Oak                | c          | Hollow Base                            | Lean                           | Fair         | 1        | No.              |                              |
| 49          | 29/21                      | Water Oak               | c          | Poor Form                              | Included Bark                  | Fair         | 3        | No               |                              |
| 50          | 255<br>235                 | Laurel Oak<br>Black Gum | 0          | Hollow Rose<br>Poor Lorm               | NON GRAND                      | Poor<br>Lair | 2        | No<br>Tes        | NA/Significant tree          |
| 52<br>52    | 23.5                       | Water Oak               | c          |  | NON GRAND                      | Fair         | 3        | Yes              | NA/Significant Tree          |
| 53          | 10/14                      | Water Oak               | - D        | V-Shaped Crotch                        | Poor Farm                      | Poss         | 3        | No               |                              |
| 54          | 26.5<br>15.5/17.5          | Weter Oak<br>Weter Oak  | P D        | Decline<br>N. Decoline                 | Starm Denage<br>Starm Denage   | Pour         | 3        | Yes.             | Steff Approvel               |
| 56          | 18/21                      | Red Oak                 | D          | V-Shaped Gratch<br>Hollow Base         | Decay                          | Poor         | 1        | Yes              | Special Ecogrism<br>Variance |
| 57          | 9/10/13                    | Post Oak                | D          | Stump Sprouts                          | Poor Farm                      | Poor         | 2        | Yes              | Variance                     |
| 58          | 9/14                       | Water Oak               | D          | V Shaped Cretch/Poor Form              | NON GRAND                      | Poor         | 3        | Yes              | NA/Significant Tree          |
| 59          | 23<br>28                   | Water Oak<br>Red Oak    | D<br>C     | Hollow/Storm Camage                    | NON GRAND                      | Poor<br>Fair | 3 2      | Yes<br>No        | NA/Significant Tree          |
| 61          | 64                         | Live Oak                | - 8        | Utility Pruned                         |                                | Good         | 1        | No               |                              |
| 62          | 17/19                      | Water Oak               | D          | Storm Damage                           | Hollow                         | Poor         | 3        | No.              |                              |
| 64          | 10.5/12/12.5               | Water Oak<br>Red Oak    | D          | Stamp Sproats                          | PoorFarm<br>PoorFarm           | Foor<br>Poor | 3        | No<br>No         |                              |
| 65          | 12/15                      | Water Oak               | D          | V-Shaped Gotah                         | Decay                          | Poor         | 3        | No               |                              |
| 66          | 12/13                      | Water Oak               | D          | Hellow                                 |                                | Poer         | 3        | Yes              | Special Exception            |
| 67          | 8.7/14.6                   | Water Oak               | - C<br>- B | Deorg                                  | NON GRAND                      | Fair         | 3        | No<br>No         |                              |
| 60          | 11/12.5                    | Live Oak<br>Laurel Oak  | 0          | Stump Sprouts/Pear Form                | NON GRAND                      | Good         | 2        | Yes              | NA/Significant Tree          |
| 70          | 23.5                       | Live Oak                | c          | Storm Damage/Decay                     | NON GRAND                      | Fair         | 1        | No               |                              |
| 71          | 7/21                       | Live Oak                |            |  |                                | Good         | 1        | No               |                              |
| 72          | 8.5/11/15.5                | Live Oak<br>Water Oak   | B<br>D     | Stump Sproets                          | PoorFerm                       | Good<br>Poor | 3        | No<br>Yes        | Special Exception            |
| 74          | 12/13/14.5                 | Water Oak               | D          | Stump Sprouts                          | Poor Farm                      | Poor         | 1        | Yes              | Special Exception            |
| 75          | 32/16                      | Water Oak               | C          | V-Shaped Crotch                        | PoorFarm                       | Fair         | 3        | No               |                              |
| 76          | 23.5<br>B/9/11/13          | Water Oak<br>Water Oak  | E D        | V-Shaped Crotch/Decay<br>Stump Sproots | NON GRAND<br>Poor Farm         | Fair<br>Poor | 3        | No<br>Yes        | Special Exception            |
| 78          | 10/10.5/14.5               | Water Oak               | D          | Stamp Sproats                          | Decay                          | Poor         | 3        | Yes              | Special Exception            |
| 79          | 14/17.5                    | Water Oak               | D          | V-Shaped Crotch                        | Hollew                         | Poor         | 3        | No               |                              |
| 80          | 8/5/12                     | Live Oak                | C          | Decline<br>December                    | Suppressed                     | Fair         | 1        | No.              |                              |
| 81          | 8.5/15.5<br>7/10/10.5/11.5 | Water Oak<br>Water Oak  | D 0        | Poor Form<br>Sturry Sprosts            | Poor Farm                      | Poor         | 3        | No<br>Yes        | Special Exception            |
| 88          | 43.5                       | Live Oak                | c          | Hollow Base                            |                                | Fair         | 1        | No               | ,                            |
| 84          | 27.5                       | Live Oak                | C          | Lean                                   |                                | Fair         | 1        | No               |                              |
| 85<br>86    | 13/13.5                    | Water Oak<br>Water Oak  | C<br>D     | Poor Form<br>Hollow                    | PoorFarm                       | Fair<br>Poor | 3        | No<br>No         |                              |
| 87          | 9/13/13.5                  | Water Oak               | D          | Stump Sprouts                          | Poor Farm                      | Poor         | 3        | No.              |                              |
| 88          | 12.5/13                    | Water Oak               | C          | Poor Form                              |                                | Fair         | 3        | No               |                              |
| 85<br>90    | 27.5                       | Water Oak<br>Water Oak  | D C        | V-Shaped Crotch<br>Poor Form           | Storm Damage<br>NON GRAND      | Poor<br>Fair | 3        | No<br>No         |                              |
| 91          | 8/9/9                      | Live Oak                | c          | POUR PORTS                             | HON GROUD                      | Fair         | 1        | Yes              | Variance                     |
| 92          | 13/18                      | Water Oak               | D          | V-Shaped Grotch                        | Hollow                         | Poor         | 3        | Yes              | Special Exception            |
| 93          | 12.5/14                    | Water Oak               | D          | V-Shaped Crotch                        | Hollew                         | Poor         | 3        | Yes              | Special Exception            |
| 94          | 6.5/8.5/9.5/11.5<br>7/8/9  | Maple<br>Maple          | D E        | Stump Sprouts<br>Stump Sprouts         | Dedine                         | Poor<br>Poor | 1 1      | No<br>Yes        | Staff Approval               |
| 96          | 13/14/16                   | Maple                   | 0          | Stump Sprouts                          |                                | Poor         | 1        | No               | Jan regge and                |
| 97          | 12/17.5                    | Water Oak               | D          | V-Shaped Crotch                        | Hollew                         | Poor         | 3        | No               |                              |
| 98          | 10/14                      | Water Oak               | D<br>B     | Stump Sprouts                          |                                | Poor         | 3        | No<br>No         |                              |
| 100         | 12/17<br>14/17/18          | Live Cak<br>Water Oak   | B<br>D     | Stump Sprouts                          | Hollew                         | Good         | 3        | No<br>Yes        | Special Exception            |
| 101         | 12.5/12.5                  | Hickory                 | С          | V-Shaped Crotch                        | Poor Farm                      | Fair         | 2        | No               |                              |
| 102         | 12.5/13.5/13.5             | Water Oak               | D          | Stump Sproets                          | Separate Trees                 | Poor         | 3        | Yes              | NA/Significant Tree          |
| 305         | 38.5                       | Water Oak               | D          | V-Shaped Crotch                        | Hollow                         | Poor         | 3        | Yes              | Special Exception            |







SUMMARY TABLES
THE HAMLET AT MAYBANK HIGHWAY
TIUS No. 27900-00-055, 056 & 057
PREPARED FOR: MIDDLEBURG REAL ESTATE PARTNERS
MYYBANK HIGHWAY
GITY OF GRARLESTON COUNTY, 80



DATE

08/08/2021

DRAWN/CHECKED

DML/JMD

LAST REVISED


08/12/2021

JMD

SCALE N.T.S.

PROJECT NO. 933 SHEET NUMBER

C001



- DOUBLE TRUNK THEE - THIPLE TRUNK THEE - QUADRUPLE - QUINTUPLE

\* PLEASE NOTE THAT NOT ALL THE TREES HAVE BEEN EVALUATED BY A CEPTIFIED ARBORIST AT THE TIME OF THE

| PARCEL LINE TABLE |              |         |  |  |  |  |  |  |
|-------------------|--------------|---------|--|--|--|--|--|--|
| LINE #            | DIRECTION    | LENGTH  |  |  |  |  |  |  |
| L1                | \$14'34'51"W | 6.84    |  |  |  |  |  |  |
| L2                | \$58'14'19"W | 29.84   |  |  |  |  |  |  |
| 1.3               | N1612'58'E   | 253.06  |  |  |  |  |  |  |
| L4                | N61°53'06'W  | 85.22"  |  |  |  |  |  |  |
| L5                | \$12'25'19'W | 311.86  |  |  |  |  |  |  |
| 1.6               | 558'23'05"W  | 26.95   |  |  |  |  |  |  |
| L7                | S58'45'44"W  | 79.02"  |  |  |  |  |  |  |
| L8                | \$56'22'51"W | 149.14" |  |  |  |  |  |  |
| L9                | N60'07'45"E  | 166.10  |  |  |  |  |  |  |
| L10               | S57109"42"W  | 19.57   |  |  |  |  |  |  |
| LTT               | N3511'34"R   | 39.71   |  |  |  |  |  |  |
|                   |              |         |  |  |  |  |  |  |



The South Carolbo STATE LAS requires that exceptions give of 27 per south the south th

- OPEN TOP PIPE FOUND - REBAR AND CAP FOUND - REBAR FOUND - CONCRETE MONUMENT FOUND RBS CPA NAVO 88 - 5/8" REBAR SET - MORTH AMERICAN VERTICAL DATUM OF 1988 **NAD 83** NORTH AMERICAN DATUM OF 1983 X 24.80 - SPOT ELEVATION (HARDSCAPE) X 24.1 CONC. RCP SPOT ELEVATION (GROUND) CONCRETE RENFORCED CONCRETE PIPE - INVEST ELEVATION - WATER VALVE - WATER METER - SANCTARY SEWER MANHOLE - POLYVINYL CHLORIDE

\_\_\_\_\_

- POWER POLE - GUY WIRE - MALBOX - ELECTRICAL BOX - BOUNDARY LINE ADJACENT BOUNDARY LINE RIGHT-OF-WAY UMTS - CENTERLINE OF ROAD

---- - EXISTING CONTOUR LINE FENCE UNE
WETLAND DELINEATION LINE - OVERHEAD UTLITES

- POTABLE WATER
- ISC - ISC - ISC - UNDERGROUND COMMUNICATION CABLE. - UNDERGROUND TELEPHONE LINE - ASPHALT - CONCRETE

[-----

- NON-AQUATIC RESOURCE - WETLANDS

- GRAND TREE SETBACK

LOCATION MAP N.T.S.

DANGERFIELD ENGINERING - SUNEYIN COMMUNICATION - SUNEYING E-03.184.1893

TOPOGRAPHIC SURVEY
TMS No. 279-00-00-055, 056, 057
PREPARED FOR MIDDLEBURG COMMUNITIES
MAYBANK HWY
CITY OF CHARLESTON
CHARLESTON

THIS SURVEY REPRESENTS A TOPOGRAPHIC SURVEY OF THE UPLAND PORTIONS OF TWS No. 279-00-00-055, 279-00-03-056, AND TWS No. 279-03-00-057.

2) TMS No. 279-00-00-055 AREA-9.571 ACRES IS CURRENTLY OWNED BY ST. JOHNS CENTER, LLC.

3) TMS No. 279-00-00-056 AREA-19.845 ACRES IS CURRENTLY OWNED BY ST. JOHNS CENTER, LLC. 4) THIS No. 279-00-00-057 AREA-16,645 ACRES IS CURRENTLY OWNED BY 45 MAYBANK, LLC.

5) IN ACCORDANCE TO F.E.M.A. FLOOD INSURANCE RATE MAP. COMMUNITY PAIGL NUMBER 45019098554, DATED NOVEMBER 17, 2004, THIS PROPERTY LES WITHIN ZONE X, WHICH IS NOT A SPECIAL FLOOD HAZARD ZONE.

6) ADJACENT OWNERS ARE LISTED PER TAX RECORDS AS OF 06/07/2021.

7. THE SPECIFICAL DATAS IS BASED OF THE MOTIFS ASSECTION DATAS OF THIS CLARK SIX DIST ABJUSTED THE MAINTENENT ALL MACHINERSTRANGE ASSECTION OF THE MAINTENENT ALL MACHINERSTRANGE ASSECTION OF THE MAINTENENT OF THE MAINTENE

8) THE VERTICAL DATUM IS BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 (MAVD 88).

SO THE CHESTIANS, MARKET IS SHEETED WHICH TO DETERMINE THE LOCATION OF UNDERSTOOD UTULIES, SOME LOCATIONS ARE ACTIVE, FEED MEASUREMENTS AND SOME ARE TAKEN FRED WILLIES FEED (CALTIONS MARKED IN THE FEED OF THE WARRING THAT OUTLIES ARE ACTIVE ACTIVE AND ACCURATELY HOW THAT ALL UTILIZES ARE SHOWN ACCURATELY AND ALL UTILIZES ARE SHOWN ACCURATELY AND ALL UTILIZES ARE SHOWN ACCURATELY AND ALL UTILIZES ARE SHOWN ACC

10) THE FOLLOWING URLITTES WERE CHISENED:

10) THE FOLLOWING URLITTES WERE CHISENED:

FORTALLE ARTER: ST. ARMS WATER COMPANY
FORTALLE ARTER: ST. ARMS WATER COMPANY
FORTALLE ARTER: ST. ARMS WATER COMPANY
CAS: COMMAND REPORT
COMPANICATIONS WATER AND CONCAST CAREARSON—LOW COUNTRY

COMPANICATIONS WATER AND CONCAST CAREARSON—LOW COUNTRY

OWNERS WERE AND WATER

TO ST. ARMS WATE

11) THE EXISTING 25' DOMINION ENERGY (FORWERLY SCEAG) EASEMENTS TO BE TERMINATED

REFERENCES:
1) REFERENCE THE POLLOWING SCOOT HIGHWAY DOCKET:
4) DOCKET No. 10.586 (STAFFWOOD RD)

EU DUCHEL HIS 10.586 (STAFFROOR NU)

DESTREMENT HE POLICIAINING EED HEODISCH AT THE CHARLESTON COUNTY R.O.D.:

1) DEED BOOK (H46, PAUE 300

1) DEED BOOK H46, PAUE 300

4) DEED BOOK H17, PAUE 309

5) DEED BOOK F173, PAUE 303

7) DEED BOOK F173, PAUE 303

7) DEED BOOK F174, PAUE 303

7) DEED BOOK F174, PAUE 303

3) 1050 1000 1000 CPb., rate ner

(3) A S. 6 C. L. YOUNGEOOD CAP/L/PME PLAT TOCK H. PAGE 003

(4) A S. 6 C. L. YOUNGEOOD CAP/L/PME PLAT TOCK H. PAGE 003

(5) H. BO H. H. DON H. PAGE 003

(6) H. BO H. H. DON H. PAGE 003

(7) H. BO H. H. DON H. PAGE 003

(8) H. BO H. PAGE 003

(9) D. HARMITH NEL CAP/L/PME PLAT TOCK AV, PAGE 115

(9) D. HARMITH NEL CAP/L/PME PLAT TOCK AV, PAGE 115

(9) D. HARMITH NEL CAP/L/PME PLAT TOCK AV, PAGE 115 04/26/1983 PART BOOK AX, PAGE 111 PRINTED 05/28/1983 PART BOOK BR, PAGE 477 PAGT BOOK US, PAGE 6043 LAST REVISED 02/02/2015 Q2/24/2020 PAGE 0153 f) F. ELUOTTE QUINN g) MARK WOODROW ELLIS h) RICHARD A. ALDREDGE

4) REFERENCE A PLAT TITLED "PLAT OF LOTS 4,5,6,7,8,69 (FORMERLY LANDS OF J C SEABROOK" PREPARED BY LAWRENCE.

J. NEWMERTY DATED AUGUST 17, 2019.

 JURISDICTIONAL AND NON-JURISDICTIONAL METLANDS AS SHOWN HEREON ON TMS No. 279—00—00—055 & TMS No. 279—00—05-66 WERE REFERENCED PER USAGE FILE NUMBER SAC 2019—00528. J.RISCICTIONAL AND NON-JURISDICTIONAL METLANDS AS SHOWN HEREON ON TMS No. 279-00-00-057 WERE REPERENCED FER USACE FILE NUMBER USACE SAC 2014-01008.

7) REFERENCE ROAD CONSTRUCTION PLANS TILED "HAYES PARK SUBDIVISION ROAD CONSTRUCTION DRAWNOS NEW LEAF BULDERS LLC. 3530 MAYBANK HIGHANY-JEHNS ISLAND CITY OF CHARLESTON CITY PROJECT ID<sub>8</sub> TRC-SUB2018-0000089 PERPARED BY CANSEDA L LINTON B IQ ATED. AMAINSY 18, 2018 AND LAST REVISED JANE 23, 2018.

GRAPHIC SCALE ( 25 MART )



08/14/2021


RAWN/CHECKED DML/JMD AST REVISED


JMD SCALE 1"=200"


833

C101

IF SHEET 25 LESS THAN (22" X 24") IT 25 A REDUCED PRINT, SCALE REDUCED ACCORDING











| Tree Number | DBH (inches)       | Speices      | Grade | Comment 1                 | Comment 2     | Condition | Category | Proposed Removal | Approval Required   |
|-------------|--------------------|--------------|-------|---------------------------|---------------|-----------|----------|------------------|---------------------|
| 1           | 22/31.5/32         | Live Oak     | В     | Utility Pruned            |               | Good      | 1        | No               |                     |
| 2           | 65                 | Live Oak     | В     | Storm Damage              |               | Good      | 1        | No               |                     |
| 3           | 11/12/16           | Water Oak    | D     | Stump Sprouts             | Decay         | Poor      | 3        | No               |                     |
| 4           | 27                 | Red Oak      | D     | Broken Top                | Hollow        | Poor      | 2        | No               |                     |
| 5           | 11.5/12            | Live Oak     | В     | NON GRAND                 |               | Good      | 1        | No               |                     |
| 6           | 14.5/18            | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 7           | 31.5               | Live Oak     | С     | Vines                     | Lean          | Fair      | 1        | No               |                     |
| 8           | 8.5/10/11          | Black Cherry | D     | Stump Sprouts             | Poor Form     | Poor      | 4        | Yes              | Special Exception   |
| 9           | 26.5               | Live Oak     | С     | Hollow                    | Lean          | Fair      | 1        | No               |                     |
| 10          | 30.5               | Water Oak    | С     | Decay                     | Poor Form     | Fair      | 3        | No               |                     |
| 11          | 28                 | Water Oak    | С     | Decay                     | Poor Form     | Fair      | 3        | No               |                     |
| 12          | 55.5               | Live Oak     | В     | Storm Damage              |               | Good      | 1        | No               |                     |
| 13          | 23.5               | Laurel Oak   | В     | NON GRAND                 |               | Good      | 2        | Yes              | NA/Significant Tree |
| 14          | 25                 | Red Oak      | С     | Crook                     | Poor Form     | Fair      | 2        | No               |                     |
| 15          | 25                 | Laurel Oak   | D     | Poor Form                 | Included Bark | Poor      | 2        | No               |                     |
| 16          | 29.5               | Water Oak    | D     | Decay                     | Included Bark | Poor      | 3        | Yes              | Special Exception   |
| 17          | 51                 | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 18          | 26.5               | Red Oak      | В     |                           |               | Good      | 2        | No               |                     |
| 19          | 27                 | Laurel Oak   | В     |                           |               | Good      | 2        | No               |                     |
| 20          | 23                 | Red Maple    | С     | NON GRAND                 |               | Fair      | 1        | Yes              | NA/Significant Tree |
| 21          | 25                 | Black Gum    | С     | Storm Damage              | Poor Form     | Fair      | 1        | No               |                     |
| 22          | 30                 | Elm          | D     | Broken Top                | Storm Damage  | Poor      | 4        | Yes              | Special Exception   |
| 23          | 27                 | Red Oak      | В     |                           |               | Good      | 2        | No               |                     |
| 24          | 30.5               | Laurel Oak   | С     | Storm Damage              |               | Fair      | 2        | No               |                     |
| 25          | 23.5               | Black Gum    | С     | Lean                      | NON GRAND     | Fair      | 1        | No               |                     |
| 26          | 10.5/14.5          | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 27          | 28                 | Red Oak      | В     |                           |               | Good      | 2        | No               |                     |
| 28          | 23                 | Black Gum    | D     | Crook/ Lean               | NON GRAND     | Poor      | 1        | No               |                     |
| 29          | 25.5               | Maple        | D     | Hollow                    |               | Poor      | 1        | No               |                     |
| 30          | 15.5/16            | Live Oak     | В     | Lean                      |               | Good      | 1        | No               |                     |
| 31          | 31                 | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 32          | 18/21.5            | Live Oak     | В     | Hollow Base               |               | Good      | 1        | No               |                     |
| 33          | 67                 | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 34          | 70                 | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 35          | 57.5               | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |
| 36          | 43                 | Red Oak      | В     |                           |               | Good      | 2        | No               |                     |
| 37          | 12/13              | Water Oak    | D     | V-Shaped Crotch           | Poor Form     | Poor      | 3        | No               |                     |
| 38          | 29                 | Laurel Oak   | В     | -                         |               | Good      | 2        | No               |                     |
| 39          | 23.5               | Water Oak    | D     | V-Shaped Crotch/Poor Form | NON GRAND     | Poor      | 3        | No               |                     |
| 40          | 10/14/14.5/18.5/26 | Live Oak     | В     |                           |               | Good      | 1        | No               |                     |


| 41 | 25.5         | Water Oak  | С |                           |               | Fair | 3 | No  |                     |
|----|--------------|------------|---|---------------------------|---------------|------|---|-----|---------------------|
| 42 | 28           | Laurel Oak | D | Hollow Base               | Poor Form     | Poor | 2 | No  |                     |
| 43 | 23           | Water Oak  | D | Poor Form/Lean            | NON GRAND     | Poor | 3 | No  |                     |
| 44 | 24.5         | Laurel Oak | D | Hollow                    |               | Poor | 2 | No  |                     |
| 45 | 13/35        | Live Oak   | С | Utility Pruned            |               | Fair | 1 | No  |                     |
| 46 | 33.5         | Black Gum  | В |                           |               | Good | 1 | No  |                     |
| 47 | 67.5         | Live Oak   | В |                           |               | Good | 1 | No  |                     |
| 48 | 51           | Live Oak   | С | Hollow Base               | Lean          | Fair | 1 | No  |                     |
| 49 | 19/21        | Water Oak  | С | Poor Form                 | Included Bark | Fair | 3 | No  |                     |
| 50 | 35.5         | Laurel Oak | D | Hollow Base               |               | Poor | 2 | No  |                     |
| 51 | 23.5         | Black Gum  | С | Poor Form                 | NON GRAND     | Fair | 1 | Yes | NA/Significant Tree |
| 52 | 23.5         | Water Oak  | С |                           | NON GRAND     | Fair | 3 | Yes | NA/Significant Tree |
| 53 | 10/14        | Water Oak  | D | V-Shaped Crotch           | Poor Form     | Poor | 3 | No  |                     |
| 54 | 26.5         | Water Oak  | F | Decline                   | Storm Damage  | Poor | 3 | No  | Staff Approval      |
| 55 | 15.5/17.5    | Water Oak  | D | V-Shaped Crotch           | Storm Damage  | Poor | 3 | Yes | Special Exception   |
| 56 | 18/21        | Red Oak    | D | Hollow Base               | Decay         | Poor | 1 | Yes | Variance            |
| 57 | 9/10/13      | Post Oak   | D | Stump Sprouts             | Poor Form     | Poor | 2 | Yes | Variance            |
| 58 | 9/14         | Water Oak  | D | V-Shaped Crotch/Poor Form | NON GRAND     | Poor | 3 | Yes | NA/Significant Tree |
| 59 | 23           | Water Oak  | D | Hollow/Storm Damage       | NON GRAND     | Poor | 3 | Yes | NA/Significant Tree |
| 60 | 28           | Red Oak    | С |                           |               | Fair | 2 | No  |                     |
| 61 | 61           | Live Oak   | В | Utility Pruned            |               | Good | 1 | No  |                     |
| 62 | 17/19        | Water Oak  | D | Storm Damage              | Hollow        | Poor | 3 | No  |                     |
| 63 | 10.5/14      | Water Oak  | С | Lean                      | Poor Form     | Fair | 3 | No  |                     |
| 64 | 10.5/12/12.5 | Red Oak    | D | Stump Sprouts             | Poor Form     | Poor | 2 | No  |                     |
| 65 | 12/15        | Water Oak  | D | V-Shaped Crotch           | Decay         | Poor | 3 | No  |                     |
| 66 | 12/13        | Water Oak  | D | Hollow                    |               | Poor | 3 | Yes | Special Exception   |
| 67 | 8.7/14.6     | Water Oak  | С | Decay                     | NON GRAND     | Fair | 3 | No  |                     |
| 68 | 24           | Live Oak   | В |                           |               | Good | 1 | No  |                     |
| 69 | 11/12.5      | Laurel Oak | D | Stump Sprouts/Poor Form   | NON GRAND     | Poor | 2 | Yes | NA/Significant Tree |
| 70 | 23.5         | Live Oak   | С | Storm Damage/Decay        | NON GRAND     | Fair | 1 | No  |                     |
| 71 | 7/21         | Live Oak   | В |                           |               | Good | 1 | No  |                     |
| 72 | 14.5/17      | Live Oak   | В |                           |               | Good | 1 | No  |                     |
| 73 | 8.5/11/15.5  | Water Oak  | D | Stump Sprouts             | Poor Form     | Poor | 3 | Yes | Special Exception   |
| 74 | 12/13/14.5   | Water Oak  | D | Stump Sprouts             | Poor Form     | Poor | 3 | Yes | Special Exception   |
| 75 | 12/16        | Water Oak  | С | V-Shaped Crotch           | Poor Form     | Fair | 3 | No  |                     |
| 76 | 23.5         | Water Oak  | С | V-Shaped Crotch/Decay     | NON GRAND     | Fair | 3 | No  |                     |
| 77 | 8/9/11/13    | Water Oak  | D | Stump Sprouts             | Poor Form     | Poor | 3 | Yes | Special Exception   |
| 78 | 10/10.5/14.5 | Water Oak  | D | Stump Sprouts             | Decay         | Poor | 3 | Yes | Special Exception   |
| 79 | 14/17.5      | Water Oak  | D | V-Shaped Crotch           | Hollow        | Poor | 3 | No  |                     |
| 80 | 8/9/12       | Live Oak   | С | Decline                   | Suppressed    | Fair | 1 | No  |                     |
| 81 | 8.5/15.5     | Water Oak  | D | Poor Form                 |               | Poor | 3 | No  |                     |

### Middleburg

| 82  | 7/10/10.5/11.5   | Water Oak | D | Stump Sprouts   | Poor Form      | Poor | 3 | Yes | Special Exception   |
|-----|------------------|-----------|---|-----------------|----------------|------|---|-----|---------------------|
| 83  | 43.5             | Live Oak  | С | Hollow Base     |                | Fair | 1 | No  |                     |
| 84  | 27.5             | Live Oak  | С | Lean            |                | Fair | 1 | No  |                     |
| 85  | 13/13.5          | Water Oak | С | Poor Form       |                | Fair | 3 | No  |                     |
| 86  | 31.5             | Water Oak | D | Hollow          | Poor Form      | Poor | 3 | No  |                     |
| 87  | 9/13/13.5        | Water Oak | D | Stump Sprouts   | Poor Form      | Poor | 3 | No  |                     |
| 88  | 12.5/13          | Water Oak | С | Poor Form       |                | Fair | 3 | No  |                     |
| 89  | 27.5             | Water Oak | D | V-Shaped Crotch | Storm Damage   | Poor | 3 | No  |                     |
| 90  | 23               | Water Oak | С | Poor Form       | NON GRAND      | Fair | 3 | No  |                     |
| 91  | 8/9/9            | Live Oak  | С |                 |                | Fair | 1 | Yes | Variance            |
| 92  | 13/18            | Water Oak | D | V-Shaped Crotch | Hollow         | Poor | 3 | Yes | Special Exception   |
| 93  | 12.5/14          | Water Oak | D | V-Shaped Crotch | Hollow         | Poor | 3 | Yes | Special Exception   |
| 94  | 6.5/8.5/9.5/11.5 | Maple     | D | Stump Sprouts   |                | Poor | 1 | No  |                     |
| 95  | 7/8/9            | Maple     | F | Stump Sprouts   | Decline        | Poor | 1 | Yes | Staff Approval      |
| 96  | 13/14/16         | Maple     | D | Stump Sprouts   |                | Poor | 1 | No  |                     |
| 97  | 12/17.5          | Water Oak | D | V-Shaped Crotch | Hollow         | Poor | 3 | No  |                     |
| 98  | 10/14            | Water Oak | D | Stump Sprouts   |                | Poor | 3 | No  |                     |
| 99  | 12/17            | Live Oak  | В |                 |                | Good | 1 | No  |                     |
| 100 | 14/17/18         | Water Oak | D | Stump Sprouts   | Hollow         | Poor | 3 | Yes | Special Exception   |
| 101 | 12.5/12.5        | Hickory   | С | V-Shaped Crotch | Poor Form      | Fair | 2 | No  |                     |
| 102 | 12.5/13.5/13.5   | Water Oak | D | Stump Sprouts   | Separate Trees | Poor | 3 | Yes | NA/Significant Tree |
| 103 | 38.5             | Water Oak | D | V-Shaped Crotch | Hollow         | Poor | 3 | Yes | Special Exception   |








#### TMS No. 279-00-00-231 CAROLYN E. SLAY ZONING: CHARLESTON COUNTY-R-4 GRAND TREE PROTECTION AREA (TYP) GRAND TREE NOT CATEGORIZED BY NATURAL DIRECTIONS (TYP) LOCATION MAP GRAND TREE SETBACK (TYP) - 3' SIDE SETBACK $\underline{\mbox{SITE}}$ DATA: 1.) THE PROPERTY IS ZONED DR-6, DIVERSE RESIDENTIAL, IN CITY OF CHARLESTON. 2.) CITY OF CHARLESTON DR-6 HEIGHT, AREA, AND SETBACK REGULATIONS: REAR SETBACK DOG PARK EXISTING 75' CENTRAL ELECTRIC POWER COOPERATIVE EASEMENT 37.5' EACH SIDE OF POWERLINE (MAYBANK 4S COMMITMENT EXCEPTION #6) (PER REF. 3g & 2f) a.) MINIMUM LOT AREA = 6.0 UNITS/ACRE (MULTI-FAM. b.) SETBACKS: SETBACKS: TOTAL FRONT AND REAR SETBACK = 20' FRONT YARD SETBACK = 10' REAR YARD SETBACK = 10' TOTAL SIDE SETBACK = 6' SOUTH/WEST SETBACK = 3' NORTH/EAST SETBACK = 3' 2 ACRES EF. 6) GRAND TREE NOT CATEGORIZED BY NATURAL DIRECTIONS (TYP) c.) BUFFERS: PROPOSED FRONT = 75' TYPE H STORMWATER d.) MAXIMUM PERCENT OF LOT OCCUPIED BY BUILDINGS: DETENTION 0.475 ACRE REQUIRED = 35% AREA=46.06 ACRES e.) MAX HEIGHT LIMITS (STRUCTURES): REQUIRED = 50'/3 STORIES EA=34.82 ACRES REA=11.24 ACRES f.) MAX. HEIGHT LIMITS (FENCES/WALLS): g.) ACCESSORY BLDGS. TO RESIDENCES SETBACK REQUIF FROM FRONT STREET = N/A FROM SIDE STREET = N/A h.) ADD'T DWELLING DISTANCE FROM FRONT LOT LINE: REQUIRED = N/A WETLAND B \* AREA=2.43 ACRES 3.) ABBREVIATIONS: N/A = NOT APPLICABLE NR = NOT REQUIRED VARIANCE REQUEST TO REDUCE 25' TYPE D BUFFER TO 10' NON-WETLAND WOTUS AREA=0.14 ACRE TMS No. 279-00-00-018 FENWICK HILLS CORPORATION ZONING: CITY OF CHARLESTON-SR-1 POD 12 PROPOSED STORMWATER - 25' TYPE D BUFFER DETENTION WETLAND C AREA=3.25 ACRES 1.328 ACRES (PER REF. 5) GRAND TREE PROTECTION WETLAND D AREA=1.49 ACRES (PER REF. 5) GRAND TREE NOT CATEGORIZED BY NATURAL DIRECTIONS (TYP) GRAND TREE TO BE REMOVED (TYP.) 25' TYPE D BUFFER -3' SIDE SETBACK -

North side of project

### The Hamlet At Maybank Highway Grand Tree Removal Summary

| Tree Number | DBH (inches)   | Speices      | Grade | Comment 1       | Comment 2     | Condition | Category | Proposed Removal | Approval Required |
|-------------|----------------|--------------|-------|-----------------|---------------|-----------|----------|------------------|-------------------|
| 8           | 8.5/10/11      | Black Cherry | D     | Stump Sprouts   | Poor Form     | Poor      | 4        | Yes              | Special Exception |
| 16          | 29.5           | Water Oak    | D     | Decay           | Included Bark | Poor      | 3        | Yes              | Special Exception |
| 22          | 30             | Elm          | D     | Broken Top      | Storm Damage  | Poor      | 4        | Yes              | Special Exception |
| 54          | 26.5           | Water Oak    | F     | Decline         | Storm Damage  | Poor      | 3        | Yes              | Staff Approval    |
| 55          | 15.5/17.5      | Water Oak    | D     | V-Shaped Crotch | Storm Damage  | Poor      | 3        | Yes              | Special Exception |
| 56          | 18/21          | Red Oak      | D     | Hollow Base     | Decay         | Poor      | 1        | Yes              | Variance          |
| 57          | 9/10/13        | Post Oak     | D     | Stump Sprouts   | Poor Form     | Poor      | 2        | Yes              | Variance          |
| 66          | 12/13          | Water Oak    | D     | Hollow          |               | Poor      | 3        | Yes              | Special Exception |
| 73          | 8.5/11/15.5    | Water Oak    | D     | Stump Sprouts   | Poor Form     | Poor      | 3        | Yes              | Special Exception |
| 74          | 12/13/14.5     | Water Oak    | D     | Stump Sprouts   | Poor Form     | Poor      | 3        | Yes              | Special Exception |
| 77          | 8/9/11/13      | Water Oak    | D     | Stump Sprouts   | Poor Form     | Poor      | 3        | Yes              | Special Exception |
| 78          | 10/10.5/14.5   | Water Oak    | D     | Stump Sprouts   | Decay         | Poor      | 3        | Yes              | Special Exception |
| 82          | 7/10/10.5/11.5 | Water Oak    | D     | Stump Sprouts   | Poor Form     | Poor      | 3        | Yes              | Special Exception |
| 91          | 8/9/9          | Live Oak     | С     |                 |               | Fair      | 1        | Yes              | Variance          |
| 92          | 13/18          | Water Oak    | D     | V-Shaped Crotch | Hollow        | Poor      | 3        | Yes              | Special Exception |
| 93          | 12.5/14        | Water Oak    | D     | V-Shaped Crotch | Hollow        | Poor      | 3        | Yes              | Special Exception |
| 95          | 7/8/9          | Maple        | F     | Stump Sprouts   | Decline       | Poor      | 1        | Yes              | Staff Approval    |
| 100         | 14/17/18       | Water Oak    | D     | Stump Sprouts   | Hollow        | Poor      | 3        | Yes              | Special Exception |
| 103         | 38.5           | Water Oak    | D     | V-Shaped Crotch | Hollow        | Poor      | 3        | Yes              | Special Exception |



# Tree Save Photos

Site Photos | Tree Saves | Maybank Side -



Site Photos |Tree Saves| Maybank Side




Site Photos |Tree Saves| Maybank Side



Site Photos | Tree Saves | Maybank Side Adjacent to Northwest Detention











## Variance Trees

Variance Request #1 - Tree referenced as #56 in the arborist report. Category I (18"/21") 39" Double Red Oak with a D classification, hollow base, signs of decay and poor condition.




Variance Request #1 – Tree referenced as #56 in the arborist report. Category I (18")21") 39" Double Red Oak with a D classification, hollow base, signs of decay and poor condition.



Variance Request #1 – Tree referenced as #56 in the arborist report. Category I (18"/21") 39" Double Red Oak with a D classification, hollow base, signs of decay and poor condition.



Variance Request #2 – Tree referenced as #57 in the arborist report. Category II (9"/10"/13") 32" Triple Post Oak with a D classification, stump sprouts, poor form and poor condition.







Variance Request #3 – Tree referenced as #91 in the arborist report. Category I (8"/9"/9") 39" Tripple Live Oak with a C classification, and fair condition.



Variance Request #3 – Tree referenced as #91 in the arborist report. Category I (8"'9"/9") 39" Tripple Live Oak with a C classification, and fair condition.



Variance Request #3 – Tree referenced as #91 in the arborist report. Category I (8"/9"/9") 39" Tripple Live Oak with a C classification, and fair condition



## **Special Exception Trees**


Special Exception Request #1 – Tree referenced as #8 in the arborist report. Category IV (8.5"/10"/11") 29.5" Triple Black Cherry with a D classification, stump sprouts, poor form and poor condition.



Special Exception Request #2 – Tree referenced as #16 in the arborist report. Category III 29.5" Water Oak with a D classification, decay, included bark and poor condition.



Special Exception Request #3 – Tree referenced as #22 in the arborist report. Category IV 30" Elm with a D classification, broken top, storm damage and poor condition.



Special Exception Request #4 – Tree referenced as #55 in the arborist report. Category III (15.5"/17.5") 33" Water Oak with a D classification, V-Shaped Crotch, storm damage and poor condition.



Special Exception Request #5 – Tree referenced as #66 in the arborist report. Category III (12"/13") 25" Double Water Oak with a D classification and is hollow and in poor condition.



Special Exception Request #6 – Tree referenced as #73 in the arborist report. Category III (8.5"/11"/15.5") 35" Triple Water Oak with a D classification, stump sprouts, poor form and poor condition.



**Special Exception Request** #7 – Tree referenced as #74 in the arborist report. Category III (12"/13"/14.5") 39.5" Triple Water Oak with a D classification, stump sprouts, poor form and poor condition.



Special Exception Request #8 – Tree referenced as #77 in the arborist report. (8"/9"/11"/13") 41" Quad Water Oak, Category III, with a D classification, stump sprouts, poor form, and poor condition.



**Special Exception Request #9** – Tree referenced as #78 in the arborist report. (10"/10.5"/14.5") 35" Triple Water Oak, Category III, with a D classification, stump sprouts, decay, and poor condition.



**Special Exception Request** #10 – Tree referenced as #82 in the arborist report. (7"/10"/10.5"/11.5") 39" Quad Water Oak, Category III, with a D classification, stump sprouts, poor form, and poor condition.



**Special Exception Request** #11 – Tree referenced as #92 in the arborist report. Category III (13"/18") 31" Double Water Oak with a D classification, V-shaped crotch, hollow, and poor condition.



Special Exception Request #12 – Tree referenced as #93 in the arborist report. Category III (12.5"/14") 26.5" Double Water Oak with a D classification, V-shaped crotch, hollow, and poor condition.



Special Exception Request #13 – Tree referenced as #100 in the arborist report. Cat III (14"/17"/18") 49" Tripple Water Oak with a D classification, stump sprouts, hollow, and poor condition.



Special Exception Request #14 – Tree referenced as #103 in the arborist report. Cat III 38.5" Water Oak with a D classification, V-shaped crotch, hollow, and poor condition.

